

Background

United 241 incident

- When: November 1968
- Where: Departure from Detroit
- What: B727



Started rapid climb at 4700 ft maintaining 1G

At 6000 ft in 20-deg bank, aircraft encountered an abnormal meteorological condition

Bank increased to 40 degs and an abnormal climb rate

Captain applies forward pressure and nose-down trim

High rate of descent and difficulty recovering

-1.5G at 8700 ft and 4.7G at 1200 ft

- Why: Trim overcontrol in recovery

China Airlines 006 incident

- When: February 1985
- Where: 300 nmi NW of San Francisco, FL410
- What: 747 SP



Loss of No. 4 engine

Roll autopilot counters until it reaches limit...more roll

Almost 360 deg right roll, pitch down 69 deg

5.1g's reached during pull-up; exceeded Vmo twice

Recovered at 9,500 ft

Two serious injuries

- Why: Preoccupation with malfunction; failure to monitor instruments; likely spatial disorientation

Midwest Express 105

- When: September 1985
- Where: Milwaukee, Wisconsin
- What: DC-9

Day, VMC

Uncontained right engine failure on takeoff at 450 ft AGL

Correct then incorrect pedal, followed by aft column

Continued climbing to 700 ft, rolled right near 90 degs

Accelerated stall

- Why: Improper response to engine failure, lack of crew coordination



China Eastern Airlines 583

- When: April 1993
- Where: 950 nmi south Shemya, Alaska
- What: MD-11



Night, VMC, FL330

Inadvertent deployment of leading-edge wing slats

Several violent pitch oscillations in ensuing recovery

Simultaneous shaker and slat overspeed chime

+2.1G to -1.2G

- Why: Inadequate design of flap/slat actuation handle. Light control forces and reduced pitch stability made overcontrol easy to do

USAir 427



- When: September 1994
- Where: Approach to Pittsburgh International
- What: 737-300

At 6,000 ft, wake encounter from a leading 727

Rolled out to assigned heading, then into 28, and then
more than 70 deg roll left...shaker activates

Roll likely caused by rudder moving to stop arising
from a jam

Full aft column from pitch -30/90 deg roll until impact

Why: Rudder moved to its limit, likely in direction opposite
commanded as a result of jam in rudder power control unit

Airborne Express N827AX



- When: December 1996
- Where: Narrows, Virginia
- What: DC-8

Night, in and out of clouds, 14,000 ft

Approach-to-stall tests.

Expecting shaker at 128 kts. Got early buffet at 151

Set full power, resulting in compressor surges in No. 2

Maintained 10-14 degs pitch

Airspeed continued to decrease to full stall

Eventually applied full rudder

- Why: Inappropriate inputs in response to stall

Formosa Airlines B12255

- When: March 1998
- Where: 7 miles NW HSZ airport, Taiwan
- What: Saab 340B



Right main bus inop in preflight, but captain proceeds

Several systems unavailable

Torque split arises after attempt to equalize temps

Roll and yaw asymmetry from torque split

Potential disorientation and fatigue

- Why: Loss of situational awareness; failure to comply with MEL; likely fatigue

Korean Air Cargo 8509

- When: December 1999
- Where: Great Hallingbury, England
- What: 747-200



Night, scattered clouds 500 ft

Captain's ADI shows no bank while he increases it

Comparator alarm sounds. Flight Engineer says "bank"

Warnings canceled prior to impact at 90 deg bank

- Why: Poor crew resource management

Gulf Air 072

- When: August 2000
- Where: Persian Gulf, Bahrain
- What: A320

Dark night, VMC

On second go-around, captain commanded half the pitch req'd, and did not maintain runway heading
With TOGA and low pitch, aircraft rapidly accelerated
Flap overspeed warning; commanded flaps up
Captain deflected stick forward and got -15 deg pitch
Did not respond to multiple GPWS alerts

- Why: Likely spatial disorientation, incorrect go-around procedure, poor CRM



Icelandair 315 incident

- When: January 2002
- Where: Approach to Oslo airport
- What: B757



Day, IMC

Go around after unstable approach (near MCP alt)

After go-around transient, aircraft tries to level and
slow to MCP speed of 150 kts

Captain put in inputs to prevent stall

Pitch goes between +40/-49;

Load factor goes between 3.6 and -0.6g's

Aircraft had two more flights afterwards w/o inspection

- Why: Loss of situational awareness; mode switching challenges

Flash Airlines 604

- When: January 2004
- Where: Red Sea near Sharm el-Sheikh A/P
- What: 737-300

Night, VMC

Left turn to intercept VOR after takeoff

A/P disconnects. Captain requests heading select.

Co-pilot warned that bank was increasing

Captain neutralizes wheel, then increases right bank

Banks 111 degs and 43 pitch down

Airplane hits water at 24 degs right bank and 4G's

- Why: Findings inconclusive (disorientation? System failure?)



Pinnacle Airlines 3701

- When: October 2004
- Where: Jefferson City, Missouri
- What: CRJ-200



Night, VMC

Reposition flight; Climbed to FL410

Shaker and pusher activations; Dual engine flameout

Recovered from upset at FL340

Started performing double engine failure checklist

Did not obtain necessary speed for restart (300 kts)

Moved to APU-assisted start; unable due to core lock

- Why: Unprofessional behavior; lack of airspeed monitoring; improper response to stall; improper engine restart

Provincial Airlines C-GZKH incident



- When: May 2005
- Where: Climbout from St. John's, Newfoundland
- What: de Havilland DHC-8

Day, IMC

Inadvertently selected vertical speed mode (1190 fpm)

At 7000', engine anti-ice selected. Pneumatic not selected.

Through 8000', gradual speed decrease over 5 mins

Shaker activates at 14,800' and 104 kts

- Why: Inappropriate mode select; lack of monitoring of speed during climb out; lack of recognition of stall cues

West Caribbean Airways 708

- When: August 2005
- Where: Wreckage in Venezuela
- What: MD-82



Night, poor weather

Vertical speed mode climb to FL330...Mach EPR limited
Engine anti-ice cycled

Tried to cruise at FL 330, $M=0.75$. Again Mach EPR lim
Poor weather. Continuous speed drop.

Buffeting started. Descent requested.

Shaker activated in descent at FL320 and remained on

- Why: Lack of knowledge on operating limits, lack of speed monitoring, lack of proper response to stall

Armavia 967

- When: May 2006
- Where: Black Sea near Sochi, Russia
- What: A320

Night, IMC

Decided to divert, then decided to land

ATC instructed go-around after Wx dropped below mins

Thrust levers placed into climb; flaps and gear extended

“Speed, speed, speed” alert; Levers moved to TO/GA

Disengaged A/P, decrease pitch, banked right, used rudder

- Why: Likely spatial disorientation; poor CRM, improper go-around procedure; dual (and opposite) sidestick inputs



Adam Air 574

- When: January 2007
- Where: Makassar Strait off Indonesia
- What: 737-400

Day, IMC; stormy weather

FL350; troubleshooting IRS malfunction...A/P disconnect

Slow right roll began “bank angle” alert

Bank angle reached 100 degs; pitch 60 degs down

Pulls 3.5g (prolonged shaker) and 490 Kts

- Why: Preoccupation with troubleshooting IRSs; inadvertent A/P disconnect; possible spatial disorientation



Kenya Airways 507

- When: May 2007
- Where: Doula Intl Airport, Cameroon
- What: 737-800

Night, IMC



After takeoff, captain gave command to engage A/P

Command not acknowledged; A/P not engaged

Several heading changes input into MCP, but no A/P

Captain engages A/P and increases bank angle

Bank reaches 115 degs and pitches down at 2900 ft

Pilots used opposite inputs during attempted recovery

Bank is 60 degs at impact

- Why: Lack of monitoring, spatial disorientation, lack of crew coordination

Thomsonfly G-THOF incident

- When: September 2007
- Where: Approach to Bournemouth Airport, U.K.
- What: 737-300



Night ILS approach

Uncommanded autothrottle disengagement

Autopilot trims stabilizer up to stay on path

Go around called after aircraft slows below speed

Pitch up to 44 degs, speed 82 kts

Full column forward ineffective, trim not applied

Thrust reduced to 86%. Recovered.

- Why: Unnoticed autothrottle disconnect, lack of trim awareness and application

Aeroflot 821

- When: September 2008
- Where: Perm, Russia
- What: 737-500

Night, rainy

Approach was not stabilized

Possible western versus eastern attitude display issue

Significantly below Vref during approach

After base turn, aircraft roll 360 degs



- Why: Poor crew coordination, fatigue, spatial disorientation, captain alcohol consumption

XL Airways GXL888T

- When: November 2008
- Where: Off coast of Canet-Plage, France
- What: A320



Day, light rain

Water penetrated AoA sensors during a rinse

At FL320, AoA sensors 1 and 2 stopped moving (froze)

Later on approach, crew checked normal law protections

Stabilizer trimmed full nose up during decel

Drop to Direct Law likely unnoticed

Loss of control and crash into sea

- Why: System failure due to AoA vanes freezing. Lack of trim awareness. Lack of understanding in stall recognition

Empire Airlines 8284

- When: January 2009
- Where: Lubbock, Texas
- What: ATR-42

Night, IMC

Flap asymmetry (at F15, one side 0 and other 8-10 deg)

During troubleshooting, speed 160 to 125 kts in 26 sec

Ultimately shaker concurrent with TAWS; AoA increases

Stall; series of pitch, roll, yaw oscillations until impact

- Why: Continued approach after flap anomaly; lack of monitoring to maintain safe speed



Turkish Airlines 1951



- When: February 2009
- Where: Approach to Schiphol Airport, The Netherlands
- What: 737-800

Nonstandard ATC approach; then unstabilized approach

Left radio altimeter passed -8 feet to autothrottle

Autothrottle moved to 'retard flare' mode on approach

Autopilot increased AoA to stay on path during decel

Speed decay unnoticed until shaker activation at 460 ft

- Why: Unstable approach, lack of monitoring speed, pitch increase, and A/T mode. Stall recovery procedure improperly applied.

Colgan Air 3407

- When: February 2009
- Where: Clarence Center, New York
- What: DHC-8-400

Night VMC

Briefed Vref of 118 kts, but ref speeds switch “increase”

Shaker engaged at 131 kts, likely causing surprise


Captain pulled and resisted shaker

Tried to control roll during stall until impact

- Why: Lack of airspeed monitoring, unexpected stall warning activation, inappropriate response to stick shaker and pusher



Air France 447



- When: June 2009
- Where: International waters, Atlantic Ocean
- What: A330
 - Night IMC
 - Unreliable airspeed caused ALT 2B flight control law
 - Pilot inputs resulted in a stall
 - Stabilizer moved to nose-up limit and remained there
 - Tried to control roll during stall until impact
- Why: Unreliable airspeed procedure not applied, lack of stall recognition, recovery inputs disallowed return to safe flight

Afriqiyah Airways 771

- When: May 2010
- Where: Approach to Tripoli Intl Airport
- What: A330



Night, IMC

Continued below NDB MDA without ground visual ref
TAWS activated, then go-around

Go around pitch not maintained (nor FD commands)

Dual inputs, but not enough to cause warning

Captain took control and pushed down (F/O pulled)

- Why: Spatial disorientation, poor CRM, dual inputs, possible fatigue

Air Algerie 5017

- When: July 2014
- Where: 80 km SW of Gossi, Mali
- What: MD-83

Night

FL310, several heading changes to fly around cell

EPR erroneous on both engines (likely icing of sensors)

A/T then did not apply enough thrust

A/C slowed from 290 kts to 200 kts in 5.5 mins

A/P disengaged 20 sec after stall begins (AoA=25 deg)

Roll 140 degs, pitch down 80 degs

- Why: Crew did not activate engine anti-ice; lack of speed monitoring; lack of proper stall recovery inputs



Air Asia 8501

- When: December 2014
- Where: Karimata Strait, Indonesia
- What: A320



Dawn? (619 local) VMC

Repeated Rudder Travel Limit Unit failure at FL320

Alternate law entered after reset of FAC CBs

Sideslip from rudder causes roll and rise of FD

Pilot flying inputs results in stall

Continuous stall warning during last 3 mins

- Why: Potential ambiguous guidance on clearing failure, lack of upset training on how to recover from a full stall

Commercial Air Safety Team Study

	<i>Lack of External Visual References</i>	<i>Flight Crew Impairment</i>	<i>Training</i>	<i>Airplane Maintenance</i>	<i>Safety Culture</i>	<i>Invalid Source Data</i>	<i>Distraction</i>	<i>Systems Knowledge</i>	<i>Crew Resource Management</i>	<i>Automation Confusion / Awareness</i>	<i>Ineffective Alerting</i>	<i>Inappropriate Control Actions</i>	<i>Total</i>
Formosa Airlines Saab 340	x	x			x		x	x	x		x		7
Korean Air 747-200F	x			x		x	x		x		x		6
Flash Airlines 737-300	x		x		x		x		x	x	x	x	8
Adam Air 737-400	x		x	x			x	x	x	x	x	x	9
Kenya Airways 737-800	x		x				x		x	x	x	x	7
Aeroflot-Nord 737-500	x	x	x	x	x		x	x	x	x	x	x	11
Gulf Air A320	x		x				x		x		x	x	6
Icelandair 757-200 (Oslo)	x						x		x	x	x	x	6
Armavia A320	x	x			x		x		x	x	x	x	8
Icelandair 757-200 (Baltimore)	x				x	x	x	x	x	x	x	x	9
Midwest Express 717	x				x	x	x		x		x	x	7
Colgan Air DHC-8-Q400	x	x	x		x		x	x	x	x	x	x	10
Provincial Airlines DHC-8	x		x				x			x	x	x	6
Thomsonfly 737-800	x		x	x	x		x			x	x		7
West Caribbean MD-82	x	x			x		x	x	x	x	x	x	9
XL Airways A320		x	x	x	x	x	x	x	x	x	x		10
Turkish Airlines 737-800	x			x	x	x	x		x	x	x		8
Empire Air ATR-42	x	x			x		x		x	x	x		7
Overall	17	7	9	6	12	5	18	7	16	14	18	12	

Upset Accidents and Incidents

Why?

Lack of
attention

Lack of
understanding

Lack of
proper response

Upset Accidents and Incidents

Why?

