

General Aviation Accidents Investigative Challenges

2nd Meeting of the AIIG, 13-15 SEP 2022 Jeddah, Saudi Arabia





In general A light aircraft is an aircraft that has a maximum gross takeoff weight of 12,500 lb (5,670 kg) or less



FAA

LSA are defined as simple, low-performance, low-energy aircraft that are limited to- 1,320 pounds maximum takeoff weight for aircraft not intended for operation on water; or. 1,430 pounds maximum takeoff weight for aircraft intended for operation on water.

EASA

Light Sport Airplane (LSA) is a simple two-seater with a maximum take-off weight of 600kg. Commission Regulation (EC) No 748/2012 (Part 21) issued on August 2012, introduced a new process for the European Light Aircraft (ELA) that, together with the certification specifications CS-LSA published in 2011, create a lighter regulatory regime for the EASA certification of LSA aircraft..


Industry

There are 6 categories -- (A) Heavy, (B) B757, (C) Large Jet, (D) Large Commuter, (E) Medium, (F) Small


For Investigators it simply means NO DFDR nor CVR are required and searching for evidence is much more difficult



Ratio of General Aviation Accidents 2015-date



Ratio of fatalities of General Aviation from other operations 2015-date





Sampling of Non-Volatile Data sources









PFD G1000

_

G695 -ND







G-500

Non-Volatile Memory

Installed within display systems contain critical Flight information data.

Numerous related parameters such as: time, latitude, longitude, altitude attitude, speed, thrust...etc are extracted to recreate a flight profile.

Process Outline

Checking manuals for data availability

2 Physical search to locate and retrieve media

3 Condition of the media and Decoding Requirements

Data Analysis: Sampling of Case Studies

5 Sensible Steps for the Future





Checking if there is something Available

Search to locate and retrieve media

Where is my media? Is the data retrievable?

Which component within the wreckage to take?

 There is always an element of uncertainty. Advisable to collect "more –than- less" of damaged components.





Which units are relevant?

- Refer to the manuals.
- Contact the manufacturer.

Connectivity Inconsistency makes it difficult to extract data

Powering & Communicator connectivity

- Decide? USB/RS232/Serial Ports etc...
- Necessity of "Inhouse Cable fabrication" is real.







Media Condition & Decoding Requirements

Skills in extracting data out of the NVM Chip



- In applied electronics
- Evaluating unit condition and extreme care not to cause inadvertent removal/recovery related damage







Delicate Handling skills with:

- Fragile components
- Cable Fabrication and Software Applications


Lack of Parts/References/Vendor support


Data Decoding



Formats of Raw Data

- CSV format
- Specific proprietary format







Decoder

- Normally supplied by manufacturer
- Always "Proprietary Software"





Data Analysis: A Sampling of Case Studies



Cessna 172S

Al Thumamah (OETH)
CASE 1



Brief

On 02 FEB 2020, a Cessna 172 S, lost control and stalled shortly after takeoff from Al-Thumamah airport (OETH, near the city of Riyadh). The impact destroyed and burned the airplane killing the pilot who was the only occupant. The AIB investigators looked for NVM sources and found them.





Complete burned panel transported to AIB lab





SD Card located

Steps 1-3 for retrieving Garmin G1000 from crash site

3



SD Card Recovered






log_200922_073826_OETH.csv	Date modified: 12/24/2020 7:49 AM Size: 119 KB
log_200922_052533_OETH.csv	Date modified: 9/22/2020 5:25 AM Size: 40.0 KB
log_200922_051831_OETH.csv	Date modified: 9/22/2020 5:18 AM Size: 32.0 KB
log_200922_051251_OETH.csv	Date modified: 9/22/2020 5:15 AM Size: 104 KB
log_200922_050344_OETH.csv	Date modified: 9/22/2020 5:09 AM Size: 192 KB
log_200922_045046_OETH.csv	Date modified: 9/22/2020 4:52 AM Size: 48.0 KB
log_200921_082743csv	Date modified: 9/21/2020 828 AM Size: 40.0 KB
log_200921_075420_OETH.csv	Date modified: 9/21/2020 8:08 AM Size: 440 KB
log_200921_074808_OETH.csv	Date modified: 9/21/2020 7:49 AM Size: 48.0 KB
log_200921_060546csv	Date modified: 9/21/2020 6:24 AM Size: 576 KB
log_200921_052316_OETH.csv	Date modified: 9/21/2020 5:38 AM Size: 488 KB
log_200921_043609_OETH.csv	Date modified: 9/21/2020 4:40 AM Size: 128 KB
log_200921_043038_OETH.csv	Date modified: 9/21/2020 4:33 AM Size: 88.0 KB
log_200920_045326_OETH.csv	Date modified: 9/20/2020 4:55 AM Size: 88.0 KB
log_200919_060030_OETH.csv	Date modified: 9/19/2020 6:02 AM Size: 136 KB
log_200917_070450_OETH.csv	Date modified: 9/17/2020 7:11 AM Size: 208 KB

CSV Files


Managing Garmin G1000 - Steps 4 for accessing "Data Log" in CSV format and plotting for selected data.



Data Analysis







Tecnam Astore

Al Thumamah (OETH)
CASE 2



Brief

16 AUG 2022, a Tecnam Astore crashed shortly after takeoff from Al-Thumamah airport (OETH, near Riyadh). The impact destroyed the airplane killing the pilot who was the only occupant.

1



Unit Disassembly



DB37 harness Pin#	Dynon Harness Wire color	Function	Details
1	Red	Master Power (10-30V)	Page 4-1
2	Yellow	Keep Alive (10-30V, low current)	Page 4-1
3	Black	Master Ground	Page 2-2
4	Purple/blue	GP 1 (general purpose resistive)	Page 3-13
5	Black	Ground	Page 2-2
6	White/yellow	Oil pressure	Page 3-6
7	White/brown	Oil temperature	Page 3-6
8	Brown	Fuel pressure	Page 3-7
9	Brown/blue	Contact 1	Page 3-18
10	Brown/yellow	Contact 2	Page 3-18
11	Orange	EMS-D10 Transmit / PC Serial Receive (RS-232)	Page 4-2
	Yellow	EMS-D10 Receive / PC Serial Transmit	Page 4-2
12		(RS-232)	
13	Black	Ground (Fuel Flow)	Page 3-9
14	Yellow	Fuel flow input	Page 3-9
15	Red	Fuel flow power (12V)	Page 3-9
16	Black	Ground	Page 2-2
17	Black	Ground	Page 2-2
18	White/red	5V excitation circuit	Page 2-2
19	White/black	Auxiliary Serial Receive (RS-232)	Page 4-2
20	Orange/brown	Fuel level 1	Page 3-11
21	Orange/blue	Fuel level 2	Page 3-11
22	Purple/yellow	GP 2 (General Purpose Resistive)	Page 3-13

Guide to connect power and fabricate interface Cable

Steps 1-3 for retrieving EMS-D10 from crash site

EMS-D10 Data Retrieval





Memory module Data Extraction





- BMS-D10_sn1947_20220823_datalog.csv
- EMS-D10_sn1947_20220823_datalog.xlsx
- EMS-D10_sn1947_20220823_datalog_min_max.csv
- EMS-D10_sn1947_20220823_datalog_snapshot.csv
- EMS-D10_sn1947_20220823_datalogFAS.csv

CSV Files

Managing EMS-D10 - Steps 4 for accessing "Data Log" in CSV format and plotting for selected data.



Data Analysis



Tecnam P2002 SIERRA

Al Haridhah (Sport Flying strip)
CASE 3




Brief

05 AUG 2022, a Tecnam P2002 Sierra crashed into sea shore shortly after go around from Al Haridhah (Sport Flying strip) south of Kingdom of Saudi Arabia. The two occupants were injured.



Disassemble the unit

2



Locate memory NVM chip

3




Special tool download

Steps 1-3 for retrieving Garmin695 ND from crash site

Garmin695 ND






Data Decoding

Managing Garmin 695 - Steps 4 for accessing "RAW Data" format and analysis for selected data

5





Based on medium condition




Fire

- Melted equipment
- Risk of damage while extracting



Damage

- Risk of overheat
- Cable fabrication



Water Submerge

- Salt & Corrosion
- Risk of damage when powered up





Sensible Steps for the Future

Recommendations & Practices



Previous recommendation

Safety Recommendation AIB-2019-0191-SR-01 issued to a local flight academy

- to install SDs on all operational Garmin G1000/G950 units.
- to notify GACA Airworthiness PMI and POI of the added SD to the operating units.



Good practice

To activate and utilize any data recording capability that is installed onboard the aircraft

This simple to active the systems









Thank You for your attention

