

## International Civil Aviation Organization

CAR/SAM Regional Planning and Implementation Group (GREPECAS)

# Seventeenth Meeting of the CAR/SAM Regional Planning and Implementation Group (GREPECAS/17)

(Cochabamba, Bolivia (Plurinational State of), 21 to 25 July 2014)

#### Agenda Item 5.2: Status of air navigation deficiencies in the CAR/SAM Regions

## Reporting form on Air Navigation Deficiencies in ATM/CNS in the CAR/SAM Region

(Presented by IATA)

| SUMMARY   |  |  |  |  |  |  |  |  |
|---|--|--|--|--|--|--|--|--|
| This working paper presents a list of deficiencies found at the CAR/SAM Region by the airlines, using the reporting form on air navigation deficiencies, specified at the GREPECAS Procedural Handbook. |  |  |  |  |  |  |  |  |
| References:  • GREPECAS Procedural Handbook   |  |  |  |  |  |  |  |  |
| ICAO Strategic<br>Objetives:  | A-Safety<br>B-Air navigation capacity and efficiency |  |  |  |  |  |  |  |

#### 1. **Introduction**

- 1.1. On 30 November 2001, the ICAO Council approved the Uniform Methodology for the Identification, Assessment and Reporting of Air Navigation Deficiencies, and presented in the GREPECAS Procedural Handbook.
- 1.2. In order to enable GREPECAS to make detailed assessments of deficiencies, States and appropriate International Organizations like IATA, are expected to provide information for corresponding action.

## 2. Suggested actions

2.1. The Meeting is invited to review the **Appendix A** to this working paper, according to the procedures and methodology specified at the GREPECAS Procedural Handbook.

----

APPENDIX A

REPORTING FORM ON AIR NAVIGATION DEFICIENCIES IN ATM/CNS IN THE CAR/SAM REGION

| Identification  |  | Deficiencies   |                     |  | Corrective action |                   |                    |                     |
|---|--|--|---------------------|--|-------------------|-------------------|--------------------|---------------------|
| Requirements  | States/facilities                                | Description  | Date first reported | Remarks  | Description       | Executing<br>Body | Date of completion | Priority for action |
| Annex 15,<br>CAR/SAM ANP,<br>Doc 8126   | MMMX,<br>MPTO                                    | Non-compliance to<br>AIRAC publication   | 14 May<br>2014      | Latest example: MMMX<br>and MPTO approach charts<br>out of the AIRAC cycle (less<br>than 1 cycle)  |                   |                   |                    |                     |
| Doc8126<br>Annex15  | SCIE,<br>TAPA,<br>MMMX,<br>MROC                  | inaccurate Published coordinates   | 14 Mar<br>2014      | Ex. AIPs with differences in declared runway distances (MROC)  |                   |                   |                    |                     |
| Doc4444,<br>CAR/SAM ANP,<br>GANP,<br>CAR/SAM ATFM<br>manual,<br>Doc9426,<br>Doc9971,<br>Doc9883 | SAEF,<br>SACF,<br>SAMF,<br>SAEZ,<br>SUEO         | inefficient Separation and unusual ATFM initiatives application: a. 6 min separation on the final path b. Monthly and sometimes daily basis ATFM NOTAMs with Flow restrictions without a clear reason. | 23 Oct<br>2012      | <ul> <li>a. SAEZ -on a radar environment</li> <li>b. Some of the restrictions were: 1 ACFT every 10 or 15 minutes regardless the FL or the entry point of the FIRs.</li> </ul> |                   |                   |                    |                     |
| ANP,<br>Annex 4,<br>Doc8126   | SAEZ, SUMU,<br>Brazil, MROC.                     | outdated obstacle chart publications   | 19 May<br>2014      |  |                   |                   |                    |                     |
| Doc 4444,<br>Annex 1,<br>Annex 10 Vol.II,<br>Doc 9432   | CCS-SVMI,<br>BOG-SKBO,<br>LIM-SPIM,<br>MEX-MMMX, | <ul><li>lack of ICAO standard phraseology</li></ul>  | 21 Jun 2013         |  |                   |                   |                    |                     |

| Identification                  |  |  | Deficiencies   | Corrective action |  |  |
|---------------------------------|--|--|--|-------------------|--|--|
|                                 | EZE-SAEZ,<br>GUA-MGGT,<br>SCL-SCEL,  |  |  |                   |  |  |
| Doc4444,<br>Doc9883,<br>Doc9971 | CAR/SAM<br>states, except<br>Brazil, Cuba and<br>Peru.   | Flight Plan errors                     | IATA presented a proposal to apply the delegation of the FPL transmission as well as the related messages, according to the Doc.4444, until an agreed time previous the pushback. This procedure is currently used in USA, Europe, Australia, etc. In the CAR/SAM region Peru, Brazil and Cuba have already published this type of procedures. |                   |  |  |
| Doc 4444                        | STI – MDST LIR – MRLB GYE – SEGU UIO – SEQM SAP – MHLM TGU – MHTG AUA – TNCA PUJ – MDPC SDQ – MDSD | Late clearance issuance<br>during Taxi |  |                   |  |  |