




Lessons Learnt from CFIT

3 Main Accident Categories

- **Runway Excursion (RE)**
- **Controlled Flight Into Terrain (CFIT)**
- **Loss Of Control In-flight (LOC-I)**

Fatal accidents distribution per category 2001-2020



Major Accident Types

The leading cause of fatal accidents over the last 20 years was LOC-I.


Western-built jets above 40 seats

Source: ICAO, Cirium & Airbus databases

CFIT - Controlled Flight into (or towards) Terrain

- CFIT is used only to refer to occurrences during **airborne phases** of flight
- CFIT includes collisions with **objects extending above the surface** (for example: towers)
- CFIT can occur during **IMC** or **VMC**
- Includes instances when the flight crew is affected by **visual illusions** (e.g. black hole approaches)
- Does **not include** occurrences where the **control of the aircraft is lost**
- Does **not include** occurrences involving **intentional flight into/towards terrain** & low altitude operations

10 year moving average CFIT fatal accident rate (per million flights) per aircraft generation



CFIT fatal accident rates

-89% on CFIT fatal accidents rates from 1999 to 2019 all generations

Western-built jets above 40 seats

Source: ICAO, Cirium & Airbus databases

CFIT History



1960's : start of studies on CFIT

Early 1970's : First implementation of reactive TAWS solutions (GPWS). First NTSB recommendations



1974

First major CFIT B727 @Mt Weather



Mid 1970's : First reactive TAWS mandates by FAA



1979

CFIT - limitations of reactive TAWS DC10 @Mt Erebus

End 1970's : ICAO recommended the installation of the reactive TAWS



1980's : The A310 (1983) is the first Jetliner with Glass cockpit providing Flight Management System (FMS) for improved navigation and Navigation Displays for improved positional awareness.

1980's: Worldwide generalization of Reactive TAWS



Early 1990's : Introduction of predictive TAWS / Enhanced GPWS (EGPWS) comparing the aircraft position vs a terrain database




Mid 1990's : the last few countries mandate reactive TAWS


2000's : Worldwide generalization of predictive TAWS

FMS, Navigation Displays and TAWS have helped to reduce the CFIT fatal accident rate by 86%

Airbus Accidents Involving Hull Loss or Fatalities



Airbus Accidents Involving Hull Loss or Fatalities




ANALYSIS OF 3 CFIT

A300/A310

A320

A330/A340




Three CFIT accidents selected for detailed review

First CFIT Case

A300/A310

A320

A330/A340



Three CFIT accidents selected for detailed review

CFIT during approach – Islamabad 2010

Event Description

- The aircraft was to perform a circling approach procedure for runway 12.
- Before starting the approach, the flight crew created FMS waypoints that did not match the published approach procedures.
- Weather reports indicated rain, poor visibility, and low clouds. The aircraft descended **below the MDA** (i.e. 2 300 ft instead of maintaining 2 510 ft).
- The approach was **continued despite low visibility** and insufficient visual ground references.
- As configured in the FMS, the aircraft flew toward the waypoints inserted by the flight crew, away from the published approach path, toward the hills.
- As the aircraft neared the hills, air traffic control sent calls to the flight crew and the **TAWS** triggered **TERRAIN** and **PULL-UP** warnings with increasing severity **for more than one minute**.
- The **flight path was not corrected**. The aircraft impacted the hilly terrain 9.6 NM from the airport.

CFIT during approach – Islamabad 2010



CFIT workshops 15, 16 Dec 2021 - ICAO AFI Region

CFIT during approach – Islamabad 2010


The flight crew did not respond to multiple TAWS alerts:

- 70 seconds before the impact, the crew received the first TAWS warning **TERRAIN HEAD**
- During these last 70 seconds, the TAWS sounded **21 times** as:
 - **TERRAIN AHEAD**,
 - **PULL UP & TERRAIN AHEAD PULL UP (15 times)**.
- Despite calls from ATC and the FO (FO informed the Captain 4 times about the terrain and asked him at least 3 times to pull up), the Captain did not react to these warnings

Safety Enhancement


- **Design aspect**
Some ideas to be further matured
- **Operational aspect**
CRM reinforcement

Second CFIT Case




CFIT after Liftoff – A310 Abidjan 2000

- The aircraft flew into the sea after takeoff
- Stall warning triggered continuously after takeoff
- Investigation identified a broken angle-of-attack (AOA) vane
 - High AOA data sent to the Flight Warning System
- Crew applied the stall warning procedure in response to the spurious alert



Flight Profile from CVR



STALL WARNING PROCEDURE

 A310 FLIGHT CREW OPERATING MANUAL	PROCEDURES and TECHNIQUES	2.02.09	
		PAGE 1 / 2	
		REV 27	SEQ 001
FLIGHT CONTROLS			

RECOVERY FROM STALL WARNING (STICK SHAKER)

Whenever a stall warning (i. e. Stick Shaker activation) is experienced at low altitude, this should be considered as an immediate threat to maintaining a safe flight path.

Indications :

Stick Shaker activation

Speed symbol in the red and black strip on PFD speed scale

At the first indication of an impending stall or upon stick shaker activation, perform simultaneously the following actions :

THRUST LEVERS **TOGA**
PITCH ATTITUDE **REDUCE**

- If a risk of ground contact exists, do not reduce the pitch attitude more than necessary to allow airspeed to increase.
- After initial recovery, maintain the speed close to the stick shaker speed until it is safe to accelerate (closely monitor both the speed and the speed trend arrow).

BANK ANGLE WINGS LEVEL

SPEED BRAKES CHECK RETRACTED

- If below 20000ft and in clean configuration : R

SLATS EXTEND R

- When out of stall and if no threat of ground contact :

LANDING GEAR (If DOWN) UP

Recover normal speed and select flaps as required.

- If one engine inoperative :

POWER AND RUDDER USE WITH CARE

Safety Enhancement – Angle-of-Attack Monitoring at Takeoff

- **Broken probe monitoring**

- [0, +8°] domain between 90 kt and 110 kt
- Any sensor out of domain is rejected

- **At higher airspeed, the triplex monitoring takes over**

- If one source goes away from the others, it is rejected by the system

Safety Enhancement – Operational Considerations

STALL WARNING AT LIFT-OFF

Spurious stall warning may sound in NORMAL law, if an angle of attack probe is damaged. In this case, apply immediately the following actions:

THRUST TOGA

At the same time:


PITCH ATTITUDE 15 °

BANK WINGS LEVEL

Note: When a safe flight path and speed are achieved and maintained, if stall warning continues, consider it as spurious.

// END


Third CFIT Case



Three CFIT accidents selected for detailed review



CFIT during Go-Around – A330 Tripoli 2010

- No precision locator approach
- Fog forming over the airport before sunrise
- No visual reference with runway below minimum
- Go-around upon **TOO LOW TERRAIN**
 - AP disconnected / TOGA / CONF 3 / Gear UP
- Go-around pitch not flown / FD bars not followed
- Nose down inputs due to spatial disorientation
- A/C started to descent
- Late response to increasing TAWS alerts
 - **DON'T SINK**
 - **TOO LOW TERRAIN**
 - **PULL UP**



03:59:30.6

A330 Tripoli 2010 Descent Below the Path




FD and FPV not computed

A cockpit instrument panel display. At the top, it shows 'SPEED' with 'FPA-30' and 'NAV' buttons, and 'MDA 620' and 'A/THR'. The main display is a circular altimeter with a green upper half and a brown lower half, showing a current altitude of 13500 feet. To the left is a speed scale from 100 to 180. To the right is a vertical scale from 010 to 015. Below the altimeter is a heading scale from 7 to 11. On the right side, there are two flap selector levers labeled 'FLX M/C T' and 'CL', and a 'FULL' flap position indicator. Above the levers is a flap status indicator showing 'S' and 'F' with a green line graph. A small diagram of the aircraft's descent path is also visible in the upper right corner of the panel area.


04:00:44.6

A330 Tripoli 2010
G/A upon TAWS Alert



TOGA

TOO LOW TERRAIN





FD and FPV not computed



04:00:52.3

A330 Tripoli 2010
Pitch G/A not flown
FD Bars not followed




CFIT workshops 15, 16 Dec 2021 - ICAO AFI Region


04:01:09.8

A330 Tripoli 2010


Late Response to TAWS Alerts



PULL UP



SOMATOGRAVIC ILLUSION



CFIT during Go-Around – A330 Tripoli 2010

- First TAWS alert **TOO LOW TERRAIN** was followed by a GO-AROUND
- When subsequent TAWS alerts **DON'T SINK & TOO LOW TERRAIN & PULL UP** were triggered the flight crew did not respond in time

Safety Enhancement – Soft Go-Around

- **Classical go-around with TOGA power at light A/C weight**
 - Strong airspeed acceleration
 - High V/S
 - High pitch angle in some cases



- **Soft Go-Around**



Thrust adapted to get a
2000ft/min vertical speed



Safety Enhancement – Soft Go-Around



Safety Enhancement – Soft Go-Around

- Enables the flight crew to have an “appropriate” Go-Around thrust to reach a 2000ft/min V/S
- Prevents overspeed or high pitch angle increase, and reduce somatogravic illusions

CONCLUSION

- CFIT remains one of the main accident categories
- TAWS has proven to be efficient, significantly reducing the number of CFIT
- CFIT are still happening where responding to TAWS alerts would prevent the accident
- Absolute need to respond to TAWS alerts
- There are “non classical” CFIT, but TAWS is also designed for these cases