



# Obstacle Spot Checking OLS

Session 2.2: Data Assessment & Analysis 5 December 2017

AERODROME SAFEGUARDING WORKSHOP (Cairo, Egypt, 4-6 December 2017)

Presented by: Michelle Soliman, Aerodrome Ops Inspector General Civil Aviation Authority, United Arab Emirates





## The Raw Data

Obs. ID # WGS-84 Coordinates		D 1.4	Lit	Elevation	Height Above	Pen Amt o r		Survey	Shielded			
Latitude	Longitude	Description	Y/N	AMSL (m)	Ground (m)	m	Surface	Date	Ву	Action Required	Mitigaion Applied	
251034.95N	0562045.91E	MAST	N	213.28	45.72	48.40	Outer Horizontal	11/4/2008	6567	Obstacle light to be installed	Obstacle light installed, shielded object	
251156.65N	0562017.11E	MAST	N	478.79	174.28	313.91	Outer Horizontal	11/4/2008	6567	Obstacle light to be installed	Obstacle light installed, shielded object	
251132.67N	0561356.92E	MAST	N	277.18	82.56	112.30	Outer Horizontal	11/5/2008	6491	Nil	Shielded obstacle	
251114.60N	0561402.21E	MAST	N	304.44	125.64	139.56	Outer Horizontal	11/5/2008	6491	Nil	Shielded obstacle	
251038.43N	0561444.27E	MAST	N	336.11	58.08	171.23	Outer Horizontal	11/5/2008	6323	Nil	Shielded obstacle	
251116.48N	0561352.53E	PYLON	N	286.62	49.69	121.74	Outer Horizontal	11/5/2008	6491	Nil	Shielded obstacle	
251125.65N	0561349.74E	PYLON	N	258.99	46.60	94.11	Outer Horizontal	11/5/2008	6491	Nil	Shielded obstacle	
251132.26N	0561342.12E	PYLON	N	269.91	37.86	105.03	Outer Horizontal	11/5/2008	6491	Nil	Shielded obstacle	
250943.79N	0561543.57E	PYLON	N	186.19	40.35	21.31	Outer Horizontal	11/5/2008	6554	Nil	Shielded obstacle	
250934.75N	0561549.54E	PYLON	N	181.99	48.89	17.11	Outer Horizontal	11/5/2008	6554	Nil	Shielded obstacle	
245844.59N	0561924.61E	TERRAIN	N	201.91	0.00	37.03	Outer Horizontal	2/26/2009	6137	Nil	Shielded obstacle	
250244.66N	0561546.26E	MAST_(L)	Y	804.97	106.58	640.09	Outer Horizontal	2/26/2009		Obstacle light to be installed	Obstacle light installed	
	Latitude 251034.95N 251156.65N 251132.67N 251114.60N 251038.43N 251116.48N 251125.65N 251132.26N 250943.79N 250934.75N 245844.59N	Latitude         Longitude           251034.95N         0562045.91E           251156.65N         0562017.11E           251132.67N         0561356.92E           251114.60N         0561402.21E           251038.43N         0561444.27E           251116.48N         0561352.53E           251125.65N         0561349.74E           251132.26N         0561342.12E           250943.79N         0561543.57E           250934.75N         0561549.54E           245844.59N         0561924.61E	Latitude         Longitude           251034.95N         0562045.91E         MAST           251156.65N         0562017.11E         MAST           251132.67N         0561356.92E         MAST           251114.60N         0561402.21E         MAST           251038.43N         0561444.27E         MAST           251116.48N         0561352.53E         PYLON           251125.65N         0561349.74E         PYLON           250943.79N         0561543.57E         PYLON           250934.75N         0561549.54E         PYLON           245844.59N         0561924.61E         TERRAIN	Latitude         Longitude         Description         Y/N           251034.95N         0562045.91E         MAST         N           251156.65N         0562017.11E         MAST         N           251132.67N         0561356.92E         MAST         N           251114.60N         0561402.21E         MAST         N           251038.43N         0561444.27E         MAST         N           251116.48N         0561352.53E         PYLON         N           251125.65N         0561349.74E         PYLON         N           250943.79N         0561543.57E         PYLON         N           250934.75N         0561549.54E         PYLON         N           245844.59N         0561924.61E         TERRAIN         N	Latitude         Longitude         Description         Y/N         AMSL (m)           251034.95N         0562045.91E         MAST         N         213.28           251156.65N         0562017.11E         MAST         N         478.79           251132.67N         0561356.92E         MAST         N         277.18           251114.60N         0561402.21E         MAST         N         304.44           251038.43N         0561444.27E         MAST         N         336.11           251116.48N         0561352.53E         PYLON         N         286.62           251125.65N         0561349.74E         PYLON         N         258.99           251132.26N         0561342.12E         PYLON         N         269.91           250943.79N         0561543.57E         PYLON         N         186.19           250934.75N         0561549.54E         PYLON         N         181.99           245844.59N         0561924.61E         TERRAIN         N         201.91	Latitude         Longitude         Description         Y/N         AMSL (m)         Ground (m)           251034.95N         0562045.91E         MAST         N         213.28         45.72           251156.65N         0562017.11E         MAST         N         478.79         174.28           251132.67N         0561356.92E         MAST         N         277.18         82.56           251114.60N         0561402.21E         MAST         N         304.44         125.64           251038.43N         0561444.27E         MAST         N         336.11         58.08           251116.48N         0561352.53E         PYLON         N         268.62         49.69           251125.65N         0561349.74E         PYLON         N         258.99         46.60           251132.26N         0561342.12E         PYLON         N         269.91         37.86           250943.79N         0561543.57E         PYLON         N         186.19         40.35           250934.75N         0561549.54E         PYLON         N         181.99         48.89           245844.59N         0561924.61E         TERRAIN         N         201.91         0.00	Latitude         Longitude         Description         Y/N         AMSL (m)         Ground (m)         m           251034.95N         0562045.91E         MAST         N         213.28         45.72         48.40           251156.65N         0562017.11E         MAST         N         478.79         174.28         313.91           251132.67N         0561356.92E         MAST         N         277.18         82.56         112.30           251114.60N         0561402.21E         MAST         N         304.44         125.64         139.56           251038.43N         0561444.27E         MAST         N         336.11         58.08         171.23           251116.48N         0561352.53E         PYLON         N         286.62         49.69         121.74           251125.65N         0561349.74E         PYLON         N         258.99         46.60         94.11           251132.26N         0561342.12E         PYLON         N         269.91         37.86         105.03           250943.79N         0561543.57E         PYLON         N         186.19         40.35         21.31           250934.75N         0561549.54E         PYLON         N         181.99         48.89	Latitude         Longitude         Description         Y/N         AMSL (m)         Ground (m)         m         Surface           251034.95N         0562045.91E         MAST         N         213.28         45.72         48.40         Outer Horizontal           251156.65N         0562017.11E         MAST         N         478.79         174.28         313.91         Outer Horizontal           251132.67N         0561356.92E         MAST         N         277.18         82.56         112.30         Outer Horizontal           251114.60N         0561402.21E         MAST         N         304.44         125.64         139.56         Outer Horizontal           251038.43N         0561444.27E         MAST         N         336.11         58.08         171.23         Outer Horizontal           251116.48N         0561352.53E         PYLON         N         286.62         49.69         121.74         Outer Horizontal           251125.65N         0561349.74E         PYLON         N         258.99         46.60         94.11         Outer Horizontal           250943.79N         0561543.57E         PYLON         N         269.91         37.86         105.03         Outer Horizontal           250934.75N	Latitude         Longitude         Description         Y/N         AMSL (m)         Ground (m)         m         Surface         Date           251034.95N         0562045.91E         MAST         N         213.28         45.72         48.40         Outer Horizontal Outer Horizontal         11/4/2008           251156.65N         0562017.11E         MAST         N         478.79         174.28         313.91         Outer Horizontal Horizontal         11/4/2008           251132.67N         0561356.92E         MAST         N         277.18         82.56         112.30         Outer Horizontal Horizontal         11/5/2008           251114.60N         0561402.21E         MAST         N         304.44         125.64         139.56         Outer Horizontal         11/5/2008           251038.43N         0561444.27E         MAST         N         336.11         58.08         171.23         Outer Horizontal         11/5/2008           251116.48N         0561352.53E         PYLON         N         286.62         49.69         121.74         Outer Horizontal         11/5/2008           251125.65N         0561349.74E         PYLON         N         269.91         37.86         105.03         Outer Horizontal         11/5/2008	Latitude         Longitude         Description         Y/N         AMSL (m)         Ground (m)         m         Surface         Date         By           251034.95N         0562045.91E         MAST         N         213.28         45.72         48.40         Outer Horizontal Horizontal Horizontal Horizontal Horizontal Outer Horizontal         11/4/2008 6567           251156.65N         0562017.11E         MAST         N         478.79         174.28         313.91         Outer Horizontal Horizo	Latitude   Longitude   Description   Y/N   AMSL (m)   Ground (m)   m   Surface   Date   By   Action Required   251034.95N   0562045.91E   MAST   N   213.28   45.72   48.40   Outer   Horizontal   11/4/2008   6567   Obstacle light to be installed   Description   Descr	

Calculated Fields Added: Height Above Ground and Shielded By Management Fields Added
Action Required and Mitigation
Applied





### Filtering the Data

- Priorities
- Surface Penetrated
- Amount of Penetration
- Shielding Principles
- Actions Required
- Existing Mitigations (Restrictions)





## **Verification Data**

Obstacle Validation Checklist															
Obstacle Type	(UTM 40N Coordinates) (EG		Ht AMSL (EGM96) Pen		Surface (Survey Dates)	Lighting Req'd As per Safety study Y/N	Lighted As per Survey	Verified by OAT	Marking Req'd As per Safety study Y/N	Marked Y/N	Verified by OAT	Req'd As Spi per Safety ins	Warning Spheres installed Y/N		Remarks
Building	250715.72N		181.15	121.27	Inner Horizontal	Y	Y		N	N	NA	N	N	NA	
Building		0561928.39E	161.93	102.05	Inner Horizontal	Y	Y		N	N	NA	N	N	NA	
Building	250722.47N	0561854.25E	130.17	70.29	Inner Horizontal	Υ	Υ		N	N	NA	N	N	NA	
Flag Pole	250715.43N	0561700.05E	186.32	126.44	Inner Horizontal	Υ	Y		N	N	NA	N	N	NA	
Stadium		0561732.55E	89.76	7.27	Approach 11	Υ	N		N	N	NA	N	N	NA	
Building	250717.46N	0562112.15E	180.94	121.06	Inner Horizontal	Υ	Y		N	N	NA	N	N	NA	
Mast	250745.86N	0562059.47E	130.25	70.37	Inner Horizontal	Υ	N		Υ	Υ		N	N	NA	
Mast	250959.95N	0561034.01E	829.33	638.44	Approach 11	Υ	Y		Υ	Υ		N	N	NA	
Pylon	250756.76N	0561606.96E	144.8	27	Take off 29	Υ	Y		Υ	Υ		Υ	Υ		
Pylon	250811.37N	0561613.62E	150.48	32.7	Take off 29	Υ	N		Υ	Υ		Υ	Υ		
Pylon	250826.82N	0561625.28E	151.39	86.18	Conical	Υ	N		Υ	Y		Υ	Υ		
Mast	250833.24N	0561628.00E	178.58	110.33	Conical	Υ	N		Υ	Υ		N	N	NA	
Building	250721.14N	0561914.44E	142.93	83.05	Inner Horizontal	Υ	Y		N	N	NA	N	N	NA	
Mast	250641.84N	0562017.67E	83.74	23.86	Inner Horizontal	Υ	Y		Υ	Υ		N	N	NA	
Mast	250701.78N	0561958.84E	67.72	7.84	Inner Horizontal	Υ	N		Y	Υ	NA	N	N	NA	



## United Arab Emirates

## The Map







### The Results...




## Obstacle ID: 3384 Fujairah Tower





# CAR Part IX Reference for Lighting Requirement: Appendix 13 - 13.2.9.8 a) "...lighting may be omitted when..."

ii) "...for a circuit extensively obstructed by immovable objects ...procedures have been establish to ensure safety vertical clearance below prescribed flight paths..."





Photos: 15 October 2017

#### **Assessment:**

#### **Compliant**

...in excess of regulation...

No action required

**CAR Part IX Reference for Installed Lighting:** Appendix 13 - 13.2.10.3.33 Medium Intensity | Type B

High Intensity | Type A

#### **Inspector Comments:**

- · Flights are not permitted over this area due to established city
- Lighting applied from "ground level" in consideration of surrounding structures
- High Intensity | Type A on top is not required but no dazzle effect reported

**Surface Penetrated: Inner Horizontal** 

**Obstacle Type: Building** 


Ground Height: 159.45m



## Obstacle ID: 3291 Millennium – Fujairah Mall (Fujairah Commercial Complex)







ii) "...for a circuit extensively obstructed by immovable objects ...procedures have been establish to ensure safety vertical clearance below prescribed flight paths..."



**CAR Part IX Reference for Installed Lighting:** Appendix 13 - 13.2.10.3.28

Medium Intensity | Type A and C

#### **Inspector Comments:**

- Flights are not permitted over this area due to established city
- Lighting applied from "ground level" in consideration of surrounding structures
- Medium intensity Type A lighting on top of tower and medium intensity Type C on corners of mall structure

Photos:

15 October 2017

#### **Assessment:**

#### Compliant

...in excess of regulation...

No action required

Aeronautical Study: 19 September 2012

**Surface Penetrated: Inner Horizontal** 

**Obstacle Type: Building** 

**Ground Height: 90.66m** 



#### Obstacle ID: 4932 Stadium





CAR Part IX Reference for Lighting Requirement:

Appendix 13 - 13.2.9.7


**CAR Part IX Reference for Installed Lighting:** 

Appendix 13 - 13.2.10.3.29 High and Medium Intensity | Type A



#### **Inspector Comments:**

- High and Medium intensity lighting further to aeronautical study
- Lighting on approach side flash simultaneously
- Lighting on other side is not exactly synchronised



#### **Assessment:**

#### **Compliant**

Reference: 13.2.10.3.17

"High-intensity obstacle lights,
Type A...located on an object
shall flash simultaneously."

Action: Follow up with stadium
to review synchronisation of
lighting



Aeronautical Study: 28 October 2014

**Surface Penetrated: Approach 11** 

**Obstacle Type: Building** 


**Ground Height: 29.94m** 



Obstacle ID: 4936 **Flag Pole** 







**CAR Part IX Reference for Marking Requirement:** Appendix 13 - 13.2.9.8 c) "...marking may be omitted when...lighted by high intensity obstacle lights by day..."



**CAR Part IX Reference for Installed Lighting:** Appendix 13 - 13.2.10.3.29 High Intensity | Type A

#### **Inspector Comments:**

- High intensity lighting on top of flag pole
- · Marking not required

Photos: 15 October 2017

#### **Assessment:**

**Compliant** 

No action required

Aeronautical Study: 1 June 2015

**Surface Penetrated: Inner Horizontal Ground Height: 121.05m** 

**Obstacle Type: Flag Pole** 











Photos: 15 October 2017

**Compliant** 

CAR Part IX Reference for Lighting Requirement: Appendix 13 - 13.2.9.7

CAR Part IX Reference for Marking Requirement: Appendix 13 - 13.2.9.7 **CAR Part IX Reference for Installed Lighting:** 

Appendix 13 - 13.2.10.3.29 High Intensity | Type A

#### **Inspector Comments:**

- Obstacle 4422 is critical and shields other objects
- · Marking and lighting observed at distance

Assessment:

No action required

**Surface Penetrated: Approach 11** 

**Obstacle Type: Mast** 

Ground Height: 112.81m



Obstacle ID: 4258 Pylon





CAR Part IX Reference for Overhead Cable Marking: Appendix 13 - 13.2.9.11



Photos: 15 October 2017

**CAR Part IX Reference for Obstacle Lighting Requirement:**Appendix 13 - 13.2.9.5

**CAR Part IX Reference for Obstacle Marking Requirement:**Appendix 13 - 13.2.9.5

CAR Part IX Reference for Installed Lighting: Appendix 13 - 13.2.10.3.26 Medium Intensity | Type B

#### **Inspector Comments:**

- Obstacle is lit and marked as required
- Overhead wire is marked

**Assessment:** 

Compliant

No action required

**Surface Penetrated: Take-Off 29** 

**Obstacle Type: Pylon & Overhead Wires** 

**Ground Height: 59.34m** 



### Obstacle ID: 2029 Ultra Tech-Star Cement







#### **CAR Part IX Reference for Installed Lighting:**

Est. 45m to 150m above Ground Level Appendix 13 - 13.2.10.3.26 Medium Intensity | Type B

#### **Inspector Comments:**

- · Obstacle is well lit and visible
- Lighting does not flash simultaneously

CAR Part IX Reference for Lighting Requirement: Appendix 13 - 13.2.9.10 "...should be marked and/or lighted if an aeronautical study indicates...



Photos: 17 October 2017

#### **Assessment:**

#### **Compliant**

Reference: 13.2.10.3.17

"....medium intensity obstacle
lights, Types A and B ...located
on an object shall flash
simultaneously."

Action: Follow up regarding
synchronisation of flashing
lights

**Surface Penetrated: Conical Obstacle Type: Building** 



Obstacle ID: 2023
Pan Emirates Cement





CAR Part IX Reference for Lighting Requirement:
Appendix 13 - 13.2.9.10
"...should be marked and/or lighted if an aeronautical study indicates...

#### **Inspector Comments:**

• Facility is closed – no lighting observed



Photos: 17 October 2017

#### **Assessment:**

#### Compliant

Action: Assess facility in relation to flight procedures, elevations and surrounding area and confirm whether some lighting is required or not

**Surface Penetrated: Conical Obstacle Type: Building** 



## Obstacle ID: 1203 Du Comms Tower – Dibba Road









Photos: 17 October 2017

maintenance

CAR Part IX Reference for Installed Lighting: Est. <45m above Ground Level Appendix 13 - 13.2.10.3.20 Low Intensity | Type A or B (fixed red)

#### **Inspector Comments:**

- Lighting was not serviceable
- · Marking observed

Assessment:
Not Compliant
Action: Contact Du and
arrange for necessary


**Surface Penetrated: Inner Horizontal** 

**Obstacle Type: Comms-Mast** 



#### Obstacle ID: 1202 Etisalat Comms Tower – Dibba Road







Photos: 17 October 2017

Assessment: Compliant

#### **CAR Part IX Reference for Installed Lighting:**

Est. 45m to 150m above Ground Level
Appendix 13 - 13.2.10.3.26
Medium Intensity | Type B (flashing red) | Top
Low Intensity | Type B (fixed red) | Intermediate Level

#### **Inspector Comments:**

- Lighting Low and Medium Intensity Type B observed at night
- · Marking observed

**Surface Penetrated: Inner Horizontal** 

**Obstacle Type: Comms-Mast** 



## Obstacle ID: ID-2987 (LOCAL) Comms Tower – Airport Road near Julphar Pharmaceuticals







CAR Part IX Reference for Installed Lighting: Est. 45m to 150m above Ground Level Appendix 13 - 13.2.10.3.26 Medium Intensity | Type C (fixed red) Photos: 17 October 2017

#### **Assessment:**

**Compliant** 

Action: Has been added to OMRK verification checking – to included in next survey

#### **Inspector Comments:**

- Lighting Medium Intensity Type C observed at night
- Marking observed
- Obstacle not included on survey data

Surface Penetrated: Not included on May 2017 Survey

**Obstacle Type: Comms-Mast** 





#### **CAR Part IX Reference for Installed Lighting:**

Est. <45m above Ground Level Appendix 13 - 13.2.10.3.20 Low Intensity | Type A or B (fixed red)

Est. 45m – 150m above Ground Level Appendix 13 - 13.2.10.3.26 Medium Intensity | Type B (flashing red)

## Obstacle ID: 2031 Comms Towers at Army Camp





Photos: 17 October 2017

#### CAR Part IX Reference for Lighting Requirement:

Appendix 13 - 13.2.9.10 "...should be marked and/or lighted if an aeronautical study indicates...

#### **Assessment:**

Compliant

Action: Verify survey

#### **Inspector Comments:**

- Lighting smaller mast Low Intensity Type A or B observed at night
- Lighting larger mast Medium Intensity Type B observed at night
- Marking observed on both towers from a distance
- Only one of the comms towers appears to be included in the survey data
- Lighting applied from "ground level" in consideration of surrounding structures


**Surface Penetrated: Conical Obstacle Type: Comms-Mast** 





#### Obstacle ID: 2032 Comms Tower – RAK Bank







Photos: 17 October 2017

#### **Assessment:**

**Compliant**Action: Review
requirement for marking

#### **CAR Part IX Reference for Installed Lighting:**

Est. <45m above Ground Level Appendix 13 - 13.2.10.3.20 Low Intensity | Type A or B (fixed red)

CAR Part IX Reference for Lighting Requirement: Appendix 13 - 13.2.9.10 "...should be marked and/or lighted if an aeronautical study indicates...

#### **Inspector Comments:**

- Lighting observed
- No marking is observed

**Surface Penetrated: Conical Obstacle Type: Comms-Mast** 





## The Final Report (GCAA)

Obstacle Description	Obstacle #	Obstacle Location (latitude)	Obstacle Location (longitude)	Penetrating of the OLS (m)	Surface Penetrated	Lighting Type	Marking Confirmed as required (Yes/No)	Comments
Flag Pole	4936	250715.43 N	0561700.05 E	126.44	Inner Horizontal	Flashing White High Intensity - Type A	Not Required	CAR Part IX Reference for Marking Requirement: Appendix 13 - 13.2.9.8 c) "marking may be omitted whenlighted by high intensity obstacle lights by day"
Mast	4422	250958.97 N	0561033.95 E	671.76	Approach 11	Flashing White  High Intensity - Type A	Yes	
Pylon	4258	250756.76 N	0561606.96 E	27	Take-Off 29	Flashing Red  Medium Intensity - Type B	Yes	Overhead Wires have Warning Spheres
Mast	1256	250701.78 N	0561958.84 E	7.84	Inner Horizontal	Flashing Red  Medium Intensity - Type B	Yes	





