

Appendix 6

LIST OF DEFICIENCIES IN THE AIR NAVIGATION FIELDS
AMS

State Name	Requirements	Facilities or Services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of Corrective action	Executing Body	Target date for implementation	Priority
Angola	AMS AFI/7 Rec. 9/12	Luanda FIC	Inadequate VHF coverage of busy ATS routes	1998	Implement remote VHF stations	5 VHF stations to be installed	ENANA		U
	AMS AFI/7 Rec. 9/12	Luanda FIC	HF poor quality and unavailable in oceanic area	2004	Improve facilities	Install adequate equipment	ENANA		U
Congo	AMS AFI/7 Rec. 9/12	Brazzaville FIC	Inadequate VHF Coverage	2009	Improve facilities	Extension VHF coverage in progress	ASECNA	2015	U
Chad	AMS AFI/7 Rec 9/12	N'Djamena FIR	Inadequate VHF Coverage	2009	Improve facilities	Extension VHF coverage in progress	ASECNA	2015	U
Dem. Rep. of Congo	AMS AFI/7 Rec. 9/12	Kinshasa FIR	Inadequate VHF coverage of busy ATS routes	1998	Improve facilities	Extension VHF coverage in progress	DR Congo	2011	U
	AMS AFI/7 Rec. 9/12	Kinshasa FIR	HF poor quality Selcal not available	1998	FIC Kinshasa OP> April 2005	New installed equipment to be restored	DR Congo	2011	U
Malawi	AMS AFI/7 Rec. 9/12	FIR Lilongwe	VHF coverage incomplete	2001	Install additional VHF relay stations at Muzuzu and Zomba	Extension VHF coverage in progress. Equipment in place	Malawi		U
Nigeria	AMS AFI/7 Rec 9/12	Kano FIR	Inadequate VHF Coverage	2009	Improve facilities	Extension VHF coverage in progress	NAMA	2015	U
Somalia	AMS AFI/7 Rec. 9/12	Mogadishu ACC	Lack of VHF coverage of busy ATS ROUTES	1998	Implement remote VHF stations	Install VHF relays	Somalia		U
