# Saint Lucia Approach Unit Air Traffic Management Contingency Plan



# **TABLE OF CONTENTS**

DBJECTIVE	2
AIR TRAFFIC MANAGEMENT	2
ATS Responsibilities	2
Separation	3
Level Restrictions	3
Delegation of Airspace	3
Other measures	3
FRANSITION TO CONTINGENCY SCHEME	4
FRANSFER OF CONTROL AND COORDINATION	5
PILOTS AND OPERATOR PROCEDURES	5
OVERFLIGHT APPROVAL	6
CONTINGENCY UNIT	
POINTS OF CONTACT	7
APPENDIX 1 - AIRSPACE	9
APPENDIX 2 – AIRSPACE (VERTICAL CUT)	. 10

#### **OBJECTIVE**

This contingency plan contains arrangements to ensure the continued safety of air navigation in the event of partial or total disruption of air traffic services (ATS) and is related to ICAO Annex 11- Air Traffic Services Chapter 2, paragraph 2.28.

It is designed to provide routes, using existing airways in most cases, which will allow aircraft operators to fly through or avoid airspace within the Saint Lucia Control Zone.

#### AIR TRAFFIC MANAGEMENT

# **ATS Responsibilities**

In the event that ATS cannot be provided within Saint Lucia Control Zone, Saint Lucia Air Sea Ports Authority's (SLASPA) Air Traffic Services Unit through its Aeronautical Information Services (AIS) shall publish the corresponding NOTAM indicating the following:

- a) Time and date of the beginning of the contingency measures;
- b) Aerodrome available for landing and airspaces available for overflying traffic to be avoided;
- c) Details of the facilities and services available or not available and any limitation on ATS provision (e.g. APP, and TWR), including an expected date of restoration of service if available;
- d) Information on the provisions made for alternative services;
- e) Procedures to be followed by adjacent ATS units;
- f) Procedures to be followed by pilots; and
- g) Any other details with respect to the disruption and actions being taken that aircraft operators may find useful.

.

In the event that the SLASPA AIS office is unable to issue the NOTAM, Martinique Civil Aviation Department through its Aeronautical Information Management Department (AIM) will take action to issue the appropriate NOTAM for Saint Lucia.

## **Delegation of Airspace**

In the event of a catastrophic ATS facility failureTMA2 (4500 feet – FL105), which is controlled by Saint Lucia, will be handed over to Martinique Approach (APP). Saint Lucia CTR (surface – 4500 feet) will be downgraded to Class G airspace. Aerodrome Control will be provided at Hewanorra and George Charles Airports. Martinique APP will provide approach control service for Saint Lucia.

#### **Separation**

Separation criteria will be applied in accordance with the *Procedures for Air Navigation Services-Air Traffic Management* (PANS-ATM, Doc 4444) and the *Regional Supplementary Procedures* (Doc 7030).

#### **Level Restrictions**

Aircraft on long-haul international flights into Saint Lucia and aircraft transiting Saint Lucia's Control Zone shall be given priority with respect to their cruising levels (*where possible*).

#### Other measures

Other measures related to the closure of airspace and the implementation of the contingency scheme in Saint Lucia Control Zone may be taken as follows:

- a) Adjacent Units shall inform Martinique Approach when it becomes apparent that communication has been lost with the Saint Lucia APP.
- b) Martinique APP shall broadcast on Frequency121.000 MHz an advisory that contingency measures have been put in place if applicable.

Note that Saint Lucia APP has internal contingencies for the use of hand held devices for such broadcast.

- c) Pilots immediately upon becoming aware of a loss of communication with Saint Lucia APP Unit shall, if operating in accordance with IFR:
  - maintain the last assigned altitude and other clearances, and
  - attempt to contact Saint Lucia APP on other published ATC frequencies for Saint Lucia.

**Note:** If unable to contact Saint Lucia APP, pilots are to attempt contact with Martinique APP on frequency 121.000 MHz or self- transfer to appropriate adjacent Units.

- d) Departing traffic from airports within Saint Lucia Control Zone shall:
  - Maintain VFR,
  - Restrict climb to 4500 feet or below, and
  - Contact Martinique APP for further onward clearances.
- e) All VFR flights both international and domestic will be required to file a flight plan.
- f) All Special VFR operations will be suspended.
- g) VFR departures shall be permitted at a rate of one (1) departure every ten (10) minutes from each airport
- h) VFR arrivals shall be permitted at a rate of one (1) every ten (10) minutes
- i) Scheduled commercial IFR operations can be permitted at a rate to arrive over the BNE or SLU Navigational Aids (NAVAIDs) at a rate not exceeding one (1) every ten (10) minutes and a departure not exceeding one (1) every ten (10) minutes.
- j) General Aviation and International Non-Scheduled carriers shall obtain prior permission for operations.

#### TRANSITION TO CONTINGENCY SCHEME

During times of uncertainty, when airspace closures seem possible, aircraft operators should be prepared for a possible change in routing while en-route.

In the event of airspace closure that has not been promulgated, Saint Lucia APP should, if possible, broadcast to all aircraft in its airspace about the closure and inform pilots to stand by for further instructions.

#### TRANSFER OF CONTROL AND COORDINATION

Except by prior coordination, the transfer of communications between Saint Lucia APP and other ATS units shall be executed before the common boundary. In the event of total communication failure Martinique APP will coordinate with other ATS units on behalf of Saint Lucia APP.

Saint Lucia APP unit shall review current coordination requirements in light of contingency operations or short notice of airspace closure as deemed necessary.

#### PILOTS AND OPERATOR PROCEDURES

Pilots need to be aware that in light of current international circumstances, a contingency routing requiring aircraft to operate outside of normal traffic flows, could result in an intercept by military aircraft.

Aircraft operators must therefore be familiar with international intercept procedures contained in ICAO. Annex 2 –*Rules of the Air*, paragraph 3.8 and Appendix 2, Sections 2 and 3.

Pilots need to continuously guard the VHF emergency frequency 121.500 MHz and should operate their transponder at all times during flight, regardless of whether the aircraft is within or outside airspace where secondary surveillance radar (SSR) is used for ATS purposes.

Transponders should be set on a discrete code assigned by ATC or select code 2000 if ATC has not assigned a code.

If an aircraft is intercepted by military aircraft, the pilot shall immediately:

a) Follow the instructions given by the intercepting aircraft, interpreting and

responding to visual signals in accordance with international procedures;

b) Notify, if possible, the appropriate ATS Unit;

c) Attempt to establish radio communication with the intercepting aircraft by making a

general call on the emergency frequency 121.500 MHz and 243.000 MHz if

equipped; and

d) Set transponder to code 7700, unless otherwise instructed by the appropriate ATS

Unit.

If any instructions received by radio from any source conflict with those given by the

intercepting aircraft, the intercepted aircraft shall request immediate clarification while

continuing to comply with the instructions given by the intercepting aircraft

OVERFLIGHT APPROVAL

Aircraft operators should obtain over-flight approval from SLASPA for flights operating

through the Saint Lucia Control Zone, where required.

In a contingency situation, flights may be rerouted at short notice and it may not be

possible for operators to give the required advanced notice in a timely manner to obtain

approval.

States/Territories/International Organizations responsible for the airspace in which

contingency routes are established should consider making special arrangements to

expedite flight approvals in these contingency situations.

**CONTINGENCY UNIT** 

The ATM National Contingency Unit assigned the responsibility of monitoring developments

that may dictate the enforcement of the contingency plan and coordination of contingency

arrangements is:

Name of Agency : Saint Lucia Air & Sea Ports Authority

Contact Person : Kendell Peter

**Telephone** : +1 758 457-6116 **Mobile** : +1 758 721-9336

Email: Kendell.peter@slaspa.com

During a contingency situation, the ATM National Contingency Unit will inform the ICAO NACC Office and adjacent ATS Units.

## **POINTS OF CONTACT**

#### **Points of Contact for Saint Lucia ANS Department**

NAME	POSITION	TELEPHONE/CELL	E-MAIL
AMY CHARLES	DIRECTOR OF AIRPORTS	W: +1 758 457 6115	amy.charles@slaspa.com
		M: +1 758 728 4854	
KENDELL PETER	MANAGER –	W: +1 758 457 6116	Kendell.peter@slaspa.com
	AIR NAVIGATION SERVICES	M: +1 758 721 9336	
LYNDEN LEONCE	TECHNICAL OFFICER –	W: +1 758 457 6167	lynden.leonce@slaspa.com
	AIR NAVIGATION SERVICES	M: +1 758 728 4867	
REMY AVRIL	SENIOR ATC OFFICER	M: +1 758 728 4886	remy.avril@slaspa.com
		O: +1 758 457 6167	
RICARDO CHARLES	SENIOR ATC OFFICER	M: +1 758 724 6436	ricardo.charles@slaspa.com
	AIM POINT OF CONTACT	O: +1 758 457 6167	

W: Work Desk M: Mobile O: Main Office

#### **Other Essential Points of Contact**


NAME	POSITION	TELEPHONE/CELL	E-MAIL
MARTINIQUE – ANS	ANS PERMANENT MANAGER	+596 596 93 60 75	sna-ag_iao-ld.sna-
			ag.ld@aviation-
			civile.gouv.fr
GRANTLEY ADAMS TMA	CHIEF ATC OFFICER	+1 246 428 6162	catcobgi@sunbeach.net
ARGYLE TMA	CHIEF ATC	+1 784 456 5994	catcsvg@gmail.com
EDDIAN MENDEZ	ICAO, REGIONAL OFFICER,	W: +52 55 5250 3211	emendez@icao.int
	ATM/SAR	M: +52 1 55 3643 9265	
JULIO DE SOUZA	IATA, ASSISTANT DIRECTOR	+55 112 187 4211	pereiraj@iata.org
PEREIRA	SAFETY & FLIGHT OPERATIONS		

W: Work Desk M: Mobile

# **DOCUMENT APPROVAL**

AUTHORITY	NAME & SIGNATURE	DATE
REVIEWED BY: Manager – Air Navigation Services	Mr. Kendell Peter	22/04/2025 dd/mm/yyyy
APPROVED BY: Director of Airports	Ms. Amy Charles	22/04/2025 dd/mm/yyyy

# **APPENDIX 1 - AIRSPACE**



# **APPENDIX 2 - AIRSPACE (VERTICAL CUT)**

