



INTERNATIONAL CIVIL AVIATION ORGANIZATION
AFI PLANNING AND IMPLEMENTATION REGIONAL GROUP
SECOND MEETING OF THE COMMUNICATIONS, NAVIGATION AND
SURVEILLANCE SUB-GROUP (CNS/SG/2)

(Dakar, 22-25 May 2007)

Agenda Item 5: Aeronautical Radio Navigation Service

5.1 Review of the implementation status and performance of the aeronautical radio navigation service, and identification of deficiencies and remedial action .

(Presented by the Secretariat)

SUMMARY

This paper examines the status of implementation of ARNS facilities in the AFI Region and identifies deficiencies and corrective measures for their elimination.

Action to be taken is at paragraph 3.

References:

- APIRG/15 Report
- Input from States

1. Introduction

1.1 . This paper reviews the current status of ARNS and related deficiencies in the AFI Region. The information in this paper is from ARNS deficiency report from APIRG/15 and updated information from States.

2. Discussion

2.1. **Appendix A** to this paper contains the updated list of the deficiencies affecting the aeronautical radio navigation service in the Region. It shows that 42 navigational aids required in the AFI ANP have not yet been implemented, whereas 11 installed facilities are to be repaired.

2.2 Table below provides the number of deficiencies for each type of navigational aid:

NAVAIDS	Number of deficiencies		
	To implement	To repair	Total

VOR	16	1	17
VOR/DME	17	5	22
DME	1	2	3
ILS	7	3	10
Total	42	11	52

2.3 It shows that radionavigation deficiencies are 20.51% of the reported CNS deficiencies .

3. Action by the CNS Sub-group

3.1 The CNS Sub-group is invited to:

- a) Take note of the information provided in this paper;
 - b) Review and update **Appendix A** (as required);
 - c) Urge States concerned to endeavor to implement any available remedial solutions as soon as possible;
 - d) Formulate any conclusion aimed at improving ARNS efficiency in the AFI Region.
-

Deficiencies affecting ARNS								
StateName	Requirements	Facilities or Services	Description of Deficiency	Date first reported	Comments on Deficiency	Executing Body	Target date for implementation	Priority
Angola	Navaids AFI/7, Rec. 10/4	Cuito Cuanavale	VOR/DME	1998		Implement facility ENANA	2001	U
	Navaids AFI/7, Rec. 10/4	Huambo	VOR/DME	1998	To repair	ENANA	2001	A
	Navaids AFI/7, Rec. 10/4	Kuito	VOR/DME	1998		Implement facility ENANA	2001	A
	Navaids AFI/7, Rec. 10/4	Saurimo	VOR/DME	1998		Implement facility ENANA	2001	U
Cameroon								
	Navaids AFI/7, Rec. 10/4	Bafoussam	VOR/DME	1998	Not implemented	Implement facility Cameroon		U
	Navaids AFI/7, Rec. 10/4	Maroua	VOR	1998	Not implemented	Implement facility Cameroon		U
Cote d`Ivoire								
	Navaids AF/7 Rec. 10/4	Bouake	ILS 21	1997	Unserviceable	To repair	Cote d`Ivoire	A
	Navaids Rec.10/4	Bouake	DME	2001	Unserviceable	To repair	Cote d`Ivoire	A
Dem. Rep. of Congo								
	Navaids AFI/7, Rec. 10/4	Kalemie	VOR/DME	1998	Unserviceable	To repair	DR Congo	U
	Navaids AFI/7, Rec. 10/4	Kindu	VOR	1998	Unserviceable	To repair	DR Congo	U
	Navaids AFI/7, Rec. 10/4	Kisangani	VOR/DME	1998	Unserviceable	To repair	DR Congo	A
	Navaids AFI/7 Rec. 10/4	Lubumbashi	DME	1998	unserviceable	To repair	DR Congo	A
Djibouti	Naviads AF/7 Rec. 10/4	Djibouti	VOR/DME	2002	Not implemented	Implement Facility	Djibouti	U
	Navaids AF/7 Rec. 10/4	Malabo	VOR/DME	2001	Not implemented	implement facility	ASECNA	U
Guinea Equatorial								
	Navaids AF/7 Rec. 10/4	Malabo	ILS	2001	Not implemented	implement facility	ASECNA	U

Guinea	Navaids AFI/7, Rec. 10/4	Kankan	VOR	1998	Not implemented	Implement facility	Guinea	A
	Navaids AFI/7, Rec. 10/4	Labe	VOR	1998	Not implemented	Implement facility	Guinea	A
	Navaids AFI/7, Rec. 10/4	Nzerekore	VOR	1998	Not implemented	Implement facility	Guinea	A
Kenya	Navaids AFI/7, Rec. 10/4	Mandera	VOR/DME	1998	Not implemented	Implement facility	Kenya	U
	Navaids AF/7 Rec. 10/4	Eldoret	DVOR/DME	2005	unserviceable	Implement Facility	Kenya	A
	Naviads Rec. 10/4	Garissa	DVOR/DME	2005	Unserviceable	Implement facility	Kenya	A
Lesotho	Navaids AFI/7, Rec. 10/4	Maseru	VOR/DME	2002	Not implemented	To implement	Lesotho	U
	Navaids AF/7 Rec.10/4	Maseru	ILS	2002	Not implemented	To implement	Lesotho	U
Liberia	Navaids Rec. 10/4	Robertsfield	ILS	1998	Unserviceable	To repair	Liberia	A
Libya	Navaids Rec 10/4	Benghazi	ILS	1998	Not implemented	Implement facility	Libya	U
	Navaids Rec.10/4	Sarir	VOR/DME	1998	Not implemented	Implement facility	Libya	A
	Navaids	Tripoli	ILS 09	1998	Not implemented	Implement facility	Libya	A

<i>StateName Requirements</i>	<i>Facilities or Services</i>	<i>Description of Deficiency</i>	<i>Date first reported</i>	<i>Comments on Deficiency</i>	<i>Description of Corrective action</i>	<i>Executing Body</i>	<i>Target date for implementation</i>	<i>Priority</i>
<i>Madagascar</i>								
Navaids AFI/7, Rec. 10/4	Antsiranana	VOR	1998	Unserviceable	To repair	Madagascar		U
Navaids AFI/7, Rec. 10/4	Maintirano	VOR	2002	Unserviceable	To repair	Madagascar		U
Navaids AFI/7, Rec. 10/4	Morondava	VOR	1998	Not implemented	Implement facility	Madagascar		U
Navaids AFI/7, Rec. 10/4	Nosy-Be/Fascene	VOR/DME	1998	Unserviceable	To repair	Madagascar		A
Navaids AF/7 Rec. 10/4	Nosy-Be/Fasce	ILS 23	1998	Not implemented	Implement facility	Madagascar		A
Navaids AFI/7, Rec. 10/4	Sainte Marie	VOR	1998	Not implemented	Implement facility	Madagascar		A
Navaids AF/7 Rec. 10/4	Tolagnaro	VOR	1998	Not implemented	Implement Facility	Madagascar		U
Navaids AFI/7, Toliara		VOR	1998	Not implemented	Implement facility	Madagascar		U
<i>Mali</i>								
Navaids AF/7 Rec. 10/4	Kayes	VOR	1998	Not implemented	Implement facility	Mali		U
Navaids AF/7 Rec.10/4	Kidal	VOR	1998	Not implemented	Implement facility	Mali		A
Navaids AF/7 Rec. 10/4	Nioro	VOR	1998	Not implemented	Implement facility	Mali,		A
Navaids AFI/7, Rec. 10/4	Tessalit	VOR	1998	Not implemented	Implement facility	Mali, ASECNA		U
Navaids Rec. 10/4	Tombouctou	ILS 07	1998	Not implemented	Implement facility	Mali		A
<i>Sao Tome & Principe</i>								
Navaids AFI/7, Rec. 10/4	Sao Tome	ILS 01	1998	Not implemented	Implement facility	Sao Tome & Principe		A
<i>Sierra Leone</i>								
Navaids AFI/7, Rec. 10/4	Freetown/Lungi	ILS	1999	Unserviceable	To repair	Sierra Leone	28/11/2002	U
Navaids AFI/7, Rec. 10/4	Freetown/Lungi	VOR/DME	1999	Unserviceable	To repair	Sierra Leone	28/11/2002	U

StateName	Requirements	Facilities or Services	Description of Deficiency	Date first reported	Comments on Deficiency	Description of Corrective action	Executing Body	Target date for implementation	Priority
Somalia									
	Navaids AFI/7, Rec. 10/4	Hargeisa	VOR/DME	1998	Not implemented	Implement facility	Somalia		U
	Navaids AFI/7, Rec. 10/4	Mogadishu	VOR/DME	1998	Not implemented	Implement facility	Somalia		U
Sudan									
	Navaids AFI/7, Rec. 10/4	Juba	ILS 13	1998	Not implemented	Implement facility	Sudan		A
	Navaids AFI/7, Rec. 10/4	Juba	VOR/DME	1998	Not implemented	Implement facility	Sudan		U
	Navaids AFI/7, Rec.10/4	Malakal	VOR/DME	1998	Not implemented	Implement facility	Sudan		U
	Navaids AFI/7 Rec.10/4	Port Sudan	ILS 36	1998	Not implemented	Implement facility	Sudan		U
Tanzania									
	Navaids AFI/7 Rec. 10/4	Dodoma	VOR/DME	1998	Not implemented	Implement facility	Tanzania		U
	Navaids AFI/7 Rec. 10/4	Kilimanjaro	ILS 09	1998	Not implemented	Implement facility	Tanzania		A
	Navaids AFI/7 Rec. 10/4	Mbeya	VOR/DME	1998	Not implemented	Implement facility	Tanzania		U
	Navaids AFI/7 Rec. 10/4	Mwanza	DME	1998	Not implemented	Implement facility	Tanzania		U
Zambia									
	Navaids AFI/7 Rec. 10/4	Kaoma	VOR	1998	Not implemented	Implement facility	Zambia		U
	Navaids AFI/7 Rec. 10/4	Livingstone	ILS 10	1998	Not implemented	Implement facility	Zambia		A
	Navaids AFI/7 Rec. 10/4	Solwezi	VOR	1998	Not implemented	Implement facility	Zambia		U

