

**RVSM MINIMUM DEFICIENCIES REPORTING LIST**

REDUCED VERTICAL SEPARATION MINIMA (RVSM)								
1.	AFI/RAN 8 Rec. 5/21	No safety data		No contribution to CRA	CAAs/ACCs to periodically submit data to ARMA	Target date: 1/8/2011		
2.	Annex 6	No records of Approvals/ Withdrawals	2006	RVSM safety reduction in separation	RVSM Approvals/Withdrawals to be submitted to ARMA (F2, F3)	Target date: 1/8/2011		
3.	Annex 6	No or limited Height Monitoring	2006	No monitoring of ASE	CAAs to comply with Height Monitoring Plan	Target date: 1/8/2011		

**Note:** ICAO Council definition of a Deficiency:

A deficiency is a situation where a facility, service or procedure does not comply with a regional air navigation plan approved by the Council, or with related ICAO Standards and Recommended Practices, and which situation has a negative impact on the safety, regularity and/or efficiency of international civil aviation.

--- END ---