



International Civil Aviation Organization

MIDANPIRG Air Traffic Management Sub-Group

Ninth Meeting (ATM SG/9)
(Sharm El Sheikh, Egypt, 14 – 16 November 2023)

Agenda Item 6: Air Navigation Deficiencies in the ATM/SAR fields

AIR NAVIGATION DEFICIENCIES IN THE ATM/SAR FIELDS

(Presented by the Secretariat)

SUMMARY

This working paper presents the deficiencies in the ATM and SAR fields for review and update.

Action by the meeting is at paragraph 3.

REFERENCE(S)

- MIDANPIRG/20 & RASG-MID/10 report (Muscat, Oman, 14 – 17 May 2023)

1. INTRODUCTION

1.1 The identification, assessment and reporting of Air Navigation Deficiencies represent a regular task of the MIDANPIRG and its subsidiary bodies.

2. DISCUSSION

2.1 The meeting may wish to recall that different MIDANPIRG meetings urged States to use the MID Air Navigation Deficiency Database (MANDD) for the submission of requests for addition, update, and elimination of Air Navigation Deficiencies, including the submission of a specific Corrective Action Plan (CAP) for each deficiency. The meeting reiterated that a deficiency would be eliminated only when a State submit a formal Letter to the ICAO MID Office containing the evidence(s) that mitigation measures have been implemented for the elimination of this deficiency.

2.2 The MIDANPIRG/20 meeting noted with concern that the majority of deficiencies listed in the MANDD have no specific CAP. The meeting urged States to implement the provisions of MIDANPIRG Conclusion 15/35 related to elimination of Air Navigation Deficiencies, in particular, the submission of a specific Corrective Action Plan (CAP) for each deficiency:

MIDANPIRG CONCLUSION 15/35: AIR NAVIGATION DEFICIENCIES


That, States be urged to:

- a) *use the MID Air Navigation Deficiency Database (MANDD) for the submission of requests for addition, update, and elimination of Air Navigation Deficiencies, including the submission of a specific Corrective Action Plan (CAP) for each deficiency; and*


- b) submit a Formal Letter to the ICAO MID Regional Office containing the evidence(s) that mitigation measures have been implemented for the elimination of deficiency(ies) when requesting the elimination of deficiency(ies) from the MANDD.

2.1 The meeting is invited to reviewed and updated the list of deficiencies in the ATM, and SAR fields as reflected in the MID Air Navigation Deficiency Database (MANDD) at: <https://mandd.icao.int>. The meeting noted that the total number of Air Navigation Deficiencies recorded in MANDD is 97 deficiencies compared to 105 deficiencies in MIDANPIRG/19.

2.2 A quantitative analysis of the MID States’ air navigation deficiencies is shown in the following Graphs and Table:




Graph 1. Reported Deficiencies by field (MIDANPIRG/20 vs MIDANPIRG/19)



Graph 2. Number of Air Navigation deficiencies by State (MIDANPIRG/20 vs MIDANPIRG/19)

	Bahrain	Egypt	Iran	Iraq	Jordan	Kuwait	Lebanon	Libya	Oman	Qatar	Saudi Arabia	Sudan	Syria	UAE	Yemen	Total
AOP	0	0	1	1	0	0	1	1	0	0	0	1	3	0	1	9
AIM	0	2	3	7	3	0	4	5	3	0	2	2	9	0	8	48
ATM	0	0	1	4	1	0	1	2	0	1	1	1	3	1	0	16
SAR	0	0	0	1	0	1	1	2	0	0	0	0	2	0	2	9
CNS	0	0	0	0	0	1	1	1	0	0	0	0	0	0	1	4
MET	0	0	0	1	0	0	2	2	0	0	0	0	3	0	3	11
TOTAL	0	2	5	14	4	2	10	13	3	1	3	4	20	1	15	97

Table 1. Number of Air Navigation Deficiencies by State and by Field



Graph 3. Number of ATM and SAR Deficiencies by State

2.3 *In the ATM field:* the total number of deficiencies is sixteen (16); nine (9) priority “A” and seven (7) priority “B”. Eight (8) related to the uncompleted signature of contingency agreements; seven (7) related to the non-implementation of planned regional ATS Routes; and one (1) related to unsatisfactory reporting of large Height deviation (LHD) to the MIDRMA.

2.4 *In the SAR field:* the total number of deficiencies is nine (9) priority “A”. Five (5) related to the lack of implementation of SAR provisions; and four (4) related to non-compliance with the carriage of Emergency Locator Transmitter (ELT) requirements.

2.5 The updated lists of deficiencies in the ATM and SAR fields are at **Appendices A and B**, respectively.

2.6 The meeting may wish to recalled the Decision has taken by the MIDANPIRG/20, summarized in the following items:

- a) as reported by MIDRMA, new deficiencies were proposed to be added against *Egypt* for the high percentage of extended period of expired MMR for Egyptian register aircraft; also *Lebanon* and *Kuwait* related to failure of submission of TDS data to the MIDRMA; therefore, the total number of deficiencies in the ATM field would be nineteen (19).

- b) as reported by the CNS SG/12 meeting, new deficiencies were proposed to be added against *Bahrain, Egypt, Iran, Iraq, Jordan, Kuwait, Lebanon, Oman, Qatar, Saudi Arabia, Sudan* and *UAE* for not implementing the Priority 1 AIDC/OLDI connection; therefore, the total number of deficiencies in the CNS field would be sixteen (16).

2.7 The MIDANPIRG/20 meeting agreed to allow for corrective period up to 31 December 2023, then the items in the para 2.6 will be included in the MANDD (total number of deficiencies would be 116).

3. ACTION BY THE MEETING

3.1 The meeting is invited to:

- a) review and update the list of deficiencies in the ATM and SAR fields;
- b) urge States to take necessary measures to implement the provisions of the MIDANPIRG/15 Conclusion 15/35, in particular submission of a specific Corrective Action Plan (CAP) for each deficiency; and
- c) States provide feedback regarding pending deficiencies in paragraphs 2.6 & 2.7.

Deficiencies in the ATM field										
IRAN										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	MID ANP TABLE ATM II-MID-1 MID REGION ATS ROUTE NETWORK	-	ATS routes A418/UP574 not implemented	Dec 2006	KUMUN-PAPAR segment not implemented.	S O	Corrective Action Plan has not been formally provided by the State	Iran- UAE	Dec 2021	B

Deficiencies in the ATM field										
IRAQ										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	MID ANP Table ATM II-MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route G667 not implemented	Sep 2006	Segment ALSAN-ABD not implemented	S	Corrective Action Plan has not been formally provided by the State	Iraq- Iran- Kuwait	Dec 2021	B
2	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency Agreement to be signed with Syria	S	Corrective Action Plan has not been formally provided by the State	Iraq	Dec 2021	A
3	MID ANP Table ATM II-MID-1 MID REGION	-	ATS route G795 not implemented	May 2008	RAF-BSR segment not implemented	S	Corrective Action Plan has not been formally	Iraq- Saudi Arabia	Dec 2021	B

A-3

	ATS ROUTE NETWORK						provided by the State			
4	MID ANP Table ATM II-MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route A424 not implemented	May 2008	LOTAN- LOVEK segment not implemented	O	Corrective Action Plan has not been formally provided by the State	Iraq	Dec 2021	B

Deficiencies in the ATM field										
JORDAN										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency agreements not signed with Syria.	H	Corrective Action Plan has not been formally provided by the State. State comment: due to political impact in the region Jordan is not able to complete the signature of contingency agreements with all adjacent States	Jordan	Dec 2021	A

Deficiencies in the ATM field										
LEBANON										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency agreements not signed with Syria	S	Corrective Action Plan has not been formally provided by the State	Lebanon	Dec 2021	A

Deficiencies in the ATM field										
LIBYA										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	Annex 11 Para 3.3.5.1	-	Not reporting the required data to the MIDRMA in a timely manner.	Dec 2013	-	H O	Corrective Action Plan has not been formally provided by the State	Libya	Dec 2021	A
2	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs	Dec 2014	Agreement signed only with Egypt	S O	Corrective Action Plan has not been formally provided by the State	Libya	Dec 2021	A

A-7

Deficiencies in the ATM field										
QATAR										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency agreements not signed with UAE.	S	Corrective Action Plan has not been formally provided by the State	Qatar-Bahrain	Dec 2021	A

Deficiencies in the ATM field										
SAUDI ARABIA										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Nov 2006	Contingency Agreements not signed with Iraq, Qatar and Sudan.	S	Corrective Action Plan has not been formally provided by the State	Saudi Arabia	Dec 2021	A

A-9

Deficiencies in the ATM field										
SUDAN										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be signed with all adjacent ACCs.	Dec 2014	Contingency Agreement signed only with Egypt	H S O	Corrective Action Plan has not been formally provided by the State	Sudan	Dec 2021	A

Deficiencies in the ATM field										
SYRIA										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	MID ANP Table ATM II-MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route G202 not implemented	Dec 1997	Segment DAKWE - Damascus not implemented	S	Corrective Action Plan has not been formally provided by the State	Syria	Dec 2021	B
2	MID ANP Table ATM II-MID-1 MID REGION ATS ROUTE NETWORK	-	ATS route UL602 not implemented	Dec 2003	Segments ELEXI-DRZ-GAZ not implemented.	S	Corrective Action Plan has not been formally provided by the State	Syria	Dec 2021	B
3	Annex 11 Para. 2.31	-	Development of contingency plan for implementation in the event of disruption or potential disruption of ATS and related supporting services. The Plan should also address natural disasters and public health emergencies. Contingency agreements should be	Nov 2006	No signed agreement yet	H O	Corrective Action Plan has not been formally provided by the State	Syria	Dec 2021	A

			signed with all adjacent ACCs.						
--	--	--	-----------------------------------	--	--	--	--	--	--

Deficiencies in the ATM field										
UAE										
Item No	Identification		Deficiencies			Corrective Action				
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action	
1	MID ANP Table ATM II-MID-1 MID REGION ATS ROUTE NETWORK	-	ATS routes A418/UP574 not implemented	Dec 2006	KUMUN-PAPAR segment not implemented.	S	Corrective Action Plan has not been formally provided by the State	Iran- UAE	Dec 2021	B

Deficiencies in the SAR field									
IRAQ									
Item No	Identification		Deficiencies			Corrective Action			
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination	Facilities/ Services	Executing body	Date of completion	Priority for action
1	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Apr 2012	- 0	Corrective Action Plan has not been formally provided by the State	Iraq	Dec 2021	A

Deficiencies in the SAR field										
KUWAIT										
Item No	Identification		Deficiencies				Corrective Action			
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination		Facilities/ Services	Executing body	Date of completion	Priority for action
1	Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	ELT	Non-compliance with carriage of Emergency Locator Transmitter (ELT) requirements	Apr 2012	-	O	Corrective Action Plan has not been formally provided by the State	Kuwait	Dec 2021	A

Deficiencies in the SAR field										
LEBANON										
Item No	Identification		Deficiencies				Corrective Action			
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination		Facilities/ Services	Executing body	Date of completion	Priority for action
1	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Apr 2012	-	0	Corrective Action Plan has not been formally provided by the State	Lebanon	Dec 2021	A

Deficiencies in the SAR field										
LIBYA										
Item No	Identification		Deficiencies				Corrective Action			
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination		Facilities/ Services	Executing body	Date of completion	Priority for action
1	Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	-	Non-compliance with carriage of Emergency Locator Transmitter (ELT) requirements	Dec 2014	-	H S O	Corrective Action Plan has not been formally provided by the State	Libya	Dec 2021	A
2	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Dec 2014	-	H S O	Corrective Action Plan has not been formally provided by the State	Libya	Dec 2021	A

Deficiencies in the SAR field										
SYRIA										
Item No	Identification		Deficiencies				Corrective Action			
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination		Facilities/ Services	Executing body	Date of completion	Priority for action
1	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Apr 2012	-	0	Corrective Action Plan has not been formally provided by the State	Syria	Dec 2021	A
2	Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	-	Non-compliance with carriage of Emergency Locator Transmitter (ELT) requirements	Apr 2012	-	0	Corrective Action Plan has not been formally provided by the State	Syria	Dec 2021	A

Deficiencies in the SAR field										
YEMEN										
Item No	Identification		Deficiencies				Corrective Action			
	Requirement	Facilities/ Services	Description	Date first reported	Remarks/ Rationale for non-elimination		Facilities/ Services	Executing body	Date of completion	Priority for action
1	Annex 12 Para. 2.1	-	Lack of provision of required SAR services	Apr 2012	-	O	Corrective Action Plan has not been formally provided by the State	Yemen	Dec 2021	A
2	Annex 6 Part I chap. 6 and Part II chap. 2 Annex 10, Vol III, Chap. 5 Annex 12 para. 2.6.4	-	Non-compliance with carriage of Emergency Locator Transmitter (ELT) requirements	Apr 2012	-	O	Corrective Action Plan has not been formally provided by the State	Yemen	Dec 2021	A