



To Regulate or Not to Regulate

Presented to ICAO PA-RAST

8 May 2018

By Carlo Zanetti





REGULATION

- Lengthy process – up to 5 years or more in Canada
- Risk mitigation gap
- Outcome not assured
- analysis



SAFETY CULTURE

Annex 19 requires that both States and service providers promote a positive safety culture with the aim of fostering effective safety management implementation through the SSP/SMS. This chapter provides guidance on the promotion of a positive safety culture.





ADDRESS CULTURE

- Timeline: 1 to 2 years;
- ICAO SMM, 4th Edition, Section 3.3.3.2 states:
 - There are a number of tools which are used to assess safety culture maturity, usually in combination:
 - a) questionnaires;
 - b) interviews and focus groups;
 - c) observations; and
 - d) document reviews.



CIVIL AVIATION SAFETY ALERT

- Safety Alert issued
- Safety information published
- Recommended action to stakeholders  SMS /Safety Culture
- Notification of TCCA follow-up inspection – 9 months to 1 year



TARGETED INSPECTION

- Culture check (ICAO, SMM, 4th Edition, Chapter 3)
- Compliance check
- Issue/topic focused
- Safety data collection (ICAO Annex 19, Chapter 5)



SAFETY DATA ANALYSIS

Data analysis capability allows:

- Identification of systemic and cross-cutting hazards;
- Monitoring of safety performance of a given sector, organization, system or process;
- data-driven decision-making.

RESULTS ACHIEVED?

- Analysis of data;
- Data interpretation;
- Results.





REPORTING

Report will include:

- Results from data collected;
- Analysis of data;
- Recommendations:
 - No further action required;
 - Consider regulatory action;
 - Consider publication of guidance;
 - Promotion or other.



QUESTIONS?