

TIMELINE - TRAGIC EVENTS & OPPORTUNITIES FOR IMPROVEMENTS

19 May 2016:

MS 804 Crash

08 March 2014:

MH 370 Disappearance

01 June 2009:

AF 447 Crash

Impact:

Raised a number of **concerns** with respect to the **public's trust** in international **civil aviation** and led to a series of rapid actions

May 2014:

ICAO Special Multidisciplinary meeting

June 2015:

GADSS concept made by Adhoc working group

March 2016:

ICAO Council adoption of GADSS-related global aircraft tracking initiatives



AIRFRANCE / FLIGHT 447



(1) 01:55:57am

Capt. Dubois goes on scheduled break, leaving two co-pilots in charge in the cockpit.

02:10:05am

Pitot tubes freeze. Air speed indicator goes haywire. Auto-pilot disconnects. Co-pilot Bonin now flying the plane.

(02:10:07am

Co-pilot Bonin makes disastrous decision to pull the nose of the plane up. Plane starts to climb rapidly, which soon leads to aerodynamic stall.

(1) 02:10:11am

First stall warning. Nose is still up, vertical speed increasing.

02:11:22am

Top of the rollercoaster. The plane stalls, starts to fall out of the sky—dropping at 10,000 feet per minute.

(02:11:43am

Capt. Dubois re-enters the cockpit. Says to Bonin, "What are you [expletive deleted] doing?" No one acknowledges the plane is in a stall.

(n2.12.30a)

Co-pilot Bonin says: "Am I going down now?" Apparently so discombobulated he has no idea whether the plane is going up or down.

(02:13:23am

Computer's synthetic voice announces "dual input" in the cockpit—the two copilots are putting contradictory inputs into their respective control sticks.

9 02:14:14am

Synthetic Voice: "Pull up!" But it is too late. Co-pilot Robert's last words: "We're going to crash. I can't believe it."

()02:14:28 am

Air France 447 hits the water.



Disappearance of Air France flight 447

Plane on route from Brazil to France with 228 people on board drops off radar screens at 0600 GMT





- ICAO developed GADSS Concept of Operations, released June 2017.
- Will enhance aviation safety for crew and passengers of commercial aircraft and SAR responders.
- Idea is to not lose anymore aircraft out at sea and able to locate the aircraft.
- The 2019 edition of the IAMSAR Manual contains general guidance regarding GADSS that applies to certain aircraft.

- The <u>first</u> phase commenced 1 January 2018 with Underwater Locating Device (ULD) on frequency 37.5 kHz attached to the aircraft flight recorder; and a ULD on frequency 8.8 kHz attached to the aircraft frame.
- The <u>second</u> phase commenced 8 November 2018 for the aircraft tracking function of automated reporting of position at least every 15 minutes.
- The <u>next</u> phase commences 1 January 2021 for the Autonomous Distress Tracking (ADT) function of reporting position updates at least once every minute.

- OBJECTIVES
- (1) Ensure timely detection of aircraft in distress (timely initiation of SAR actions).
- (2) Ensure tracking of aircraft in distress and timely accurate location of end of flight (accurate direction of SAR actions).
- (3) Enable efficient and effective SAR operations.
- (4) Ensure timely retrieval of flight recorder data.

- FUNCTIONS
- (1) Aircraft Tracking
- (2) Autonomous Distress Tracking (ADT)
- (3) Post flight localization and recovery

AUTONOMOUS DISTRESS TRACKING (ADT)

- The ADT function would be used to identify the location of an aircraft in distress with the aim of establishing, to a reasonable extent, the location of an accident site within a 6 NM radius. The accuracy of position information shall, as a minimum, meet the position accuracy requirements established for Emergency Locator Transmitters (ELTs).
- There are two high-level functional objectives for an ADT system. These are to:
 - a) receive timely notice of an airplane in a distress condition to facilitate timely SAR operations; and
 - b) locate an accident site with high probability after a crash based on last known position of the aircraft.

AUTONOMOUS DISTRESS TRACKING (ADT)

- 01 January 2021
- Brand new aircraft to be outfitted with ADT device after 2021
- Applies to certain passenger & cargo aircraft.
- All aircraft with take-off weight greater than 27,000KG/30TON maximum certificated take-off mass or seating capability over 19.
- Mandated to autonomously transmit information from which a position can be determined by the operator at least once per minute when the aircraft is in distress.
- A specific technology is not mandated. One type is Cospas-Sarsat ELT Distress Tracking (ELT(DT))
- ELT(DT) expected duration of operation is 370minutes (6.2hrs)
 - Note: Not 24 hours like an ELT
- Distress can only be de-activated using the same mechanism that it was activated originally in case of recovery from distress
- Aircraft will be allowed to replace installed Automatic Fixed ELTs with ADT devices.
 - Consequence loss of homing and exact location

Global Aeronautical Distress Safety System



Autonomous Distress Tracking

Only protected aeronautical safety spectrum, or protected distress spectrum (e.g., 406.1 MHz), can be used

- Provides automatic A/C position at least once every minute
- Must be active prior to accident event
- Location of an accident site within 6 NM
- Operates autonomously of aircraft power
- Results in Distress signal to appropriate aircraft operator
- May be manually activated
- · Cannot be isolated





ELT (DT)

- COSPAS-SARSAT will start approving specialized ELTs for Distress Tracking (DT) in 2019
- Does not have the 121.5 MHz homing capability
 - May optionally equip 121.5 MHz homing
- Linked to new COSPAS-SARSAT system, alerts will be sent to RCCs
- Transmits position, aircraft ID and country of origin
- There will be a notification on the alert which will indicate whether if the ELT(DT) is in flight or has crashed
- For only 370minutes (6.2hrs)
- Every 5 seconds the first 2 minutes
- Every 10 seconds 2-5 minutes
- Every 30 seconds after 5 minutes
- There will be a part in the SIT report which states the age of the latest alert received. I.E "position 23-34.44N 070-33-.55W is less than 1 minute old"
- The only way to cancel the distress alert is by having the same reason it was activated solved

ELT (DT)

Activated when the plane is still flying via 4 main automatic triggers (manual activation available)

(1) **Unusual attitude**

The conditions may include, but are not limited to, excessive values of roll, pitch and yaw and their corresponding rates of change.

(2) <u>Unusual speed</u>

The conditions may include, but are not limited to, excessive vertical speed, stall condition, low airspeed, overspeed or other speed conditions.


(3) Collision with terrain

The conditions may include, but are not limited to, high rate of closure to terrain or inappropriate altitude for the current position.

(4) Total loss of thrust/propulsion on all engines

The parametric data used to define this condition may be engine performance parameters or other parameters that result from loss of thrust.





AUTONOMOUS DISTRESS TRACKER

