



UK State Safety Partnerships

Caribbean Destinations

Working in Safety Partnerships








To work in safety partnerships with States and their industry to enhance operational safety performance

Crown Overseas Territories

Territories



Focus on Safety (not being a regulator)

A330 excursion October 2017








Size- UVF classed as a Code 4E Aerodrome

4 denotes field length >1800m and accommodates wingspan of less than 65m and outer main gear span <14m








All Caribbean MORs [Mandatory Occurrence Reporting]








Destinations with >15 MORs








All Caribbean Crew not at Fault >20 MORs







Unreported damage
Unsecured load
Shifts
Electronic Mobility Aids
Drugs
Dangerous Goods
Escaped animals

- Aircraft Damage
- TCAS
- ATC


- Loading
- Airprox
- Weather/Turbulence

- Wildlife
- Loadsheet
- Ground Ramp/RWY

Loading








Wildlife Hazard Management







Wildlife- Diverted river channel alongside RWY and poor drainage lead to ideal environment for wildlife





Significant bird activity present

- Plovers Sand pipers
- Barn Swallows*
- > Herons
- Egrets*-large flocks seen to south of RWY and by parking stands, 20-30 birds in areas of mown grass-see next slide

Dead egret collected from RWY during inspection after AA aircraft had bird strike on departure

- ➤ Significant areas of long grass surround RWY
- ➤ Areas adjacent to RWY and pads are kept short
- ➤ Grass cutting is daily but hampered by rainfall

*seen during inspection

Egret colonies











State Safety Partnerships

UK Civil Aviation Authority International Group

Aviation House Gatwick Airport South West Sussex RH6 0YR United Kingdom

www.caa.co.uk/statesafetypartnerships